

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/20/2017

Submitted Date:

10/23/2017

Document Number:

682402913**FIELD INSPECTION FORM**
 Loc ID 449376 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 26580Name of Operator: BURLINGTON RESOURCES OIL & GAS LPAddress: PO BOX 4289City: FARMINGTON State: NM Zip: 87499**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
		COPColoradoReg@conocophillips.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449377	WELL	XX	02/27/2017		001-10007	Aspen 3-65 15-14 3H_D	CI
449378	WELL	XX	02/27/2017		001-10008	Aspen 3-65 15-14 2DH	CI

**General Comment:**

This is a Construction and Stormwater Inspection in response to Form 42: Notice of construction- Document #401430798.

**Location Construction**

Location ID: 449376 CDP: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Form 2A COAs:****Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Wildlife BMPs:****Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present
WADDLES	Yes		

Comments: Erosion BMPs: Operator constructing approach for the entrance of location. Operator has cut/mowed disturbance area and has installed a temporary BMP (i.e., filterxx wattle) around the entire perimeter of the location. Refer to the attached inspection photos for more detail.

Other BMPs:

\_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Comment:** A follow-up inspection will occur at a future date to ensure the Operator is in compliance with Rule 1000 series standards.

**Corrective  
Action:**

\_\_\_\_\_

Date: \_\_\_\_\_

**On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Inspected Facilities**Facility ID: 449377 Type: WELL API Number: 001-10007 Status: XX Insp. Status: CIFacility ID: 449378 Type: WELL API Number: 001-10008 Status: XX Insp. Status: CI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682402914	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4281334">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4281334</a>