

**FORM
22**Rev
05/13**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

OGCC RECEPTION

Receive Date:
10/22/2017Accident Tracking No.:
401437199**ACCIDENT REPORT**

As required by Rule 602.b.

CONTACT INFORMATION☒ Initial Notice of Accident ☐ Subsequent Notice of Accident

OGCC Operator Number: 10110 Contact Name: Gary Mathews
Name of Operator: GREAT WESTERN OPERATING COMPANY LLC Phone: (970) 623-3522
Address: 1801 BROADWAY #500 Fax: ()
City: DENVER State: CO Zip: 80202 Email: gmathews@gwogco.com

DESCRIPTION OF ACCIDENT(Please be as specific as possible)

Date of Accident: 10/12/2017 Time of Accident: 2:00 PM
API Number: 05- Facility ID: 447013 Type of Facility: LOCATION
Well/Facility Name: Dittmer KE Pad Well/Facility Num: 29-032HN
County: WELD
Location: QTRQTR: NENW Sec: 32 Twp: 1N Rng: 66W Meridian: 6
Lat: 40.011917 Long: -104.801886
Field Name: WATTENBERG Field Number: 90750

DESCRIPTION

Provide a detailed description of the accident, problems, and cause (equipment failure, human error, etc.): actions taken to provide well control in detail::

On 10/12/2017 at approximately 1400 hrs. an unknown person called 911 in reference to a brush fire in the area of CR 4, and CR 27 in Brighton, CO. The Brighton Fire Department arrived on scene, observing a fire at the separator units at the Dittmer location (SEC 32 TWNSHP 1N RG 66W) in Weld County.

Upon arrival, the Brighton Fire Department assumed incident command of the situation. The Fire Department set un-manned ground valves to quench and cool unaffected equipment as a mitigation technique.

An employee of Select Energy Services shut in the wells at the request of the Brighton Fire Department.

Great Western's contract pumpers with Covenant Testing Technologies arrived just after the wells were shut in to verify they were shut in correctly. At this time other Great Western employees arrived and everyone staged for safety at the well heads. Once the residual gas had been vacated out of process piping, the fire was extinguished. A truck driver who was onsite ran from the fire scene and became short of breath. He was taken to the hospital, evaluated, and released. No one was injured as a result of this incident, and cause is currently under investigation by Great Western Operating Company.

OTHER NOTIFICATIONS

List the parties and agencies notified (LDG, County, BLM EPA, DOT, Local Emergency Planning Coordinator or others)

Date	Agency	Contact	Response
10/12/2017	ADCO	Chris LaMere	
10/12/2017	Weld County	Troy Swain	
10/12/2017	COGCC	Mike Leonard	

OPERATOR COMMENTS and SUBMITTAL

This form must be signed by an authorized agent of the entity making assertion.

I certify under penalty of perjury that this report has been examined by me and to the best of my knowledge is true, correct and complete.

Print Name: Ty Woodworth

Email: twoodworth@gwogco.com

Signature: _____

Title: Prod Eng Lead

Date: 10/22/2017

CONDITIONS OF APPROVAL, IF ANY:

COA Type

Description

Prior to December 1, 2017 provide subsequent Form 22 with detailed root cause analysis including documentation of processes, procedures, policies and training implemented to prevent future instances of this nature

General Comments

User Group

Comment

Comment Date

Stamp Upon
Approval

Total: 0 comment(s)

Attachment Check List

Att Doc Num

Name

Total Attach: 0 Files