

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401430016  
Date Received:  
10/16/2017

FIR RESOLUTION FORM

CA Summary:  
2 of 2 CAs from the FIR responded to on this Form  
2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1001 NOBLE ENERGY WAY  
City: HOUSTON State: TX Zip: 77070  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Abby Bazin	720-587-2356	Abby.Bazin@nblenergy.com
Tesla Dougherty	970-304-5245	tesla.dougherty@nblenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682402645  
Inspection Date: 08/17/2017 FIR Submit Date: 08/22/2017 FIR Status:

Inspected Operator Information:

Company Name: NOBLE ENERGY INC Company Number: 100322  
Address: 1625 BROADWAY STE 2200  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 445209

Location Name: LC11-13 Number: Pad County:  
Qtrqr: SWS Sec: 11 Twp: 9N Range: 59W Meridian: 6  
W  
Latitude: 40.759150 Longitude: -103.951390

FACILITY - API Number: 05-123-00 Facility ID: 445209

Facility Name: LC11-13 Number: Pad  
Qtrqr: SWS Sec: 11 Twp: 9N Range: 59W Meridian: 6  
W  
Latitude: 40.759150 Longitude: -103.951390

CORRECTIVE ACTIIONS:

1  CA# 94429

Corrective Action: Perform reclamation along portions of the interim reclamation area in accordance to Rule 1003. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until the location meets Rule 1003 standards.

Date: 10/16/2017

Response: CA COMPLETED

Date of Completion: 10/13/2017

Operator Comment: At the time of this inspection, construction activities on this pad were not yet complete and interim construction had not yet been conducted. Interim reclamation is tentatively scheduled for December 2017, pending completion of site construction activities.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of the FIR resolution acknowledges that the Oil and Gas Conservation Commission has received the Notice. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.  
  
Operator shall comply with Rule 1003 standards.

2  CA# 94430

Corrective Action: Install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices. Corrective actions from the previous inspections were not resolved therefore the corrective action dates on this inspection remain the same from the previous inspections.

Date: 05/09/2017

Response: CA COMPLETED

Date of Completion: 10/13/2017

Operator Comment: The BMPs were improved and repaired, as shown on the attachment.

COGCC Decision: Approved pending re-inspection

COGCC Representative: COGCC staff reviewed the photo log documentation provided in the attachment.  
  
Approved pending re-inspection of the FIR resolution acknowledges that the Oil and Gas Conservation Commission has received the Notice. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tesla Dougherty

Signed: \_\_\_\_\_

Title: EHS Tech

Date: 10/16/2017 8:36:17 AM

#### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401430016	FIR RESOLUTION SUBMITTED
401430028	Holliday Tombstone Response

Total Attach: 2 Files