



COLORADO

Office of Emergency Preparedness & Response

Department of Public Health & Envirc

Print date 10/30/2017

CASE NUMBER: 2017-0555 DATE ENTERED: 10/30/2017 TIME ENTERED: 13:08
WHO TOOK REPORT: GREG J/ ANN NEDROW DATE REPORTED: 10/29/2017 TIME REPORTED: 11:00:00 AM

NRC NUMBER:

CALLER: LT. JUSTIN RUPERT/ ROB STUMPS CONFIDENTIAL: PHONE: 970-581-4788

ORGANIZATION: BERTHOUD FIRE PROTECTION

STREET:

CITY: BERTHOUD COUNTY:

STATE: CO ZIP CODE:

POTENTIALLY RESPONSIBLE PARTY ANADARKO

PRP CONTACT: PRP PHONE:

ADDRESS: EMAIL:

CITY: COUNTY:

STATE: CO ZIP CODE

EVENT DATE: 10/29/2017 EVENT TIME: 9:42:00 AM

LOCATION 2596 E HWY 60 MILE MARKER:

CITY: BERTHOUD COUNTY: LARIMER

STATE: CO ZIP CODE

Latitude:

Longitude:

TYPE OF MATERIAL OIL

MATERIAL1: OIL, POSSIBLY CRUDE QUANTITY1: UNIT1: QTY TO WATER1: UNIT1:

MATERIAL2: QUANTITY2: UNIT2: QTY TO WATER2: UNIT2:

MATERIAL3: QUANTITY3: UNIT3: QTY TO WATER3: UNIT3:

SOURCE: U

SOURCE TYPE OIL WELL/WELL SITE

CAUSE: UNKNOWN

CAUSE INFORMATION: Capped oil well was found to be leaking what appeared to be crude oil. Apparently the leak was to the ground. The Fire Dept reports that they believed it was possible fracking one mile away that was the cause of the release. At the time of the call, Rick Allison with COGCC was notified by the duty officer.

MEDIUM IMPACTED: LAND

Fixed Facility Land Air Groundwater

Surface Water Waterway Impacted:

NUMBER OF DEATHS:

NUMBER OF INJURIES:

EVACUATION:

NUMBER EVACUATED:

ACTION TAKEN: Extraction Inc. (with Anadarko) was on site with a pumper truck cleaning up the spilled oil. Berms were also applied to help to contain the oil.

CDPHE NOTIFIED: COGCC: RICK ALLISON, JOHN AXELSON, GREG DERANLEAU, KENT KUSTER; HMWMD: ROB BEIERLE, RICHARD MRUZ, ED SMITH, CAREN JOHANNES, SUSAN NEWTON, KATHRYN STEWART, DAVID FOSTER; CPW

COMMENTS: Larimer County EH

RESPONDERS: EXTRACTION INC

RESPONDER COMMENTS:

ADDITIONAL COMMENTS: