

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401465629

Date Received:
11/21/2017

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 SEVENTEENTH STREET #1400

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Lorne C Prescott

970 812 5311

lprescott@laramie-energy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680101555

Inspection Date: 03/03/2017

FIR Submit Date: 03/05/2017

FIR Status: _____

Inspected Operator Information:

Company Name: LARAMIE ENERGY LLC

Company Number: 10433

Address: 1401 SEVENTEENTH STREET #1400

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 449070

Location Name: Gunderson Number: 20-03 Pad County: _____

Qtrqr: NENW Sec: 20 Twp: 9S Range: 93W Meridian: 6

Latitude: 39.266756 Longitude: -107.795281

FACILITY - API Number: 05-077-00 Facility ID: 449070

Facility Name: Gunderson Number: 20-03 Pad

Qtrqr: NENW Sec: 20 Twp: 9S Range: 93W Meridian: 6

Latitude: 39.266756 Longitude: -107.795281

CORRECTIVE ACTIONS:

1 CA# 66369

Corrective Action: File From 42 NOTICE OF CONSTRUCTION ASAP. Staff will be communicating with Management & Enforcement re: Neglect /lack of Notification.

Date: 03/06/2017

Response: CA COMPLETED

Date of Completion: 03/06/2017

Operator
Comment:

Issues resolved

COGCC Decision: _____

COGCC
Representative:

2 CA# 66370

Corrective Action: Ditches, Appropriate BMPs need to be installed along Sides of Access Road.

Date: 03/09/2017

Response: CA COMPLETED

Date of Completion: 03/06/2017

Operator
Comment: Corrective Actions Completed

COGCC Decision:

COGCC
Representative:

3 CA# 66371

Corrective Action: Wattles, Appropriate BMPs need to be installed along Soil piled off & along Access Road on Fill side and all along North edge of Location where Topsoil has been piled close to LOD.

Date: 03/09/2017

Response: CA COMPLETED

Date of Completion: 03/06/2017

Operator
Comment: Corrective Actions Completed

COGCC Decision:

COGCC
Representative:

4 CA# 66372

Corrective Action: Roughening, Appropriate BMPs need to be installed along Soil piled off & along Access Road on Fill side and all along North edge of Location where Topsoil has been piled close to LOD.

Date: 03/09/2017

Response: CA COMPLETED

Date of Completion: 03/06/2017

Operator
Comment: Corrective Actions Completed

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lorne C Prescott

Signed:

Title: Reg & Enviro Compliance

Date: 11/21/2017 10:26:35 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files