

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401470207

Date Received:

11/29/2017

Spill report taken by:

Spill/Release Point ID:

### SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

### OPERATOR INFORMATION

Name of Operator: <u>PIONEER NATURAL RESOURCES USA INC</u>	Operator No: <u>10084</u>	<b>Phone Numbers</b>
Address: <u>5205 N O'CONNOR BLVD STE 200</u>		Phone: <u>(719) 846-7898</u>
City: <u>IRVING</u> State: <u>TX</u> Zip: <u>75039</u>		Mobile: <u>( )</u>
Contact Person: <u>James Roybal</u>		Email: <u>james.roybal@pxd.com</u>

### INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 401467576

Initial Report Date: 11/25/2017 Date of Discovery: 11/24/2017 Spill Type: Recent Spill

#### Spill/Release Point Location:

Location of Spill/Release: QTRQTR NWSE SEC 32 TWP 32S RNG 66W MERIDIAN 6

Latitude: 37.211740 Longitude: -104.799570

Municipality (if within municipal boundaries): \_\_\_\_\_ County: LAS ANIMAS

#### Reference Location:

Facility Type: WELL  Facility/Location ID No \_\_\_\_\_  
 No Existing Facility or Location ID No.  
 Well API No. (Only if the reference facility is well) 05-071-06296

#### Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes  
*Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

Were Five (5) barrels or more spilled? No

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): <u>0</u>	Estimated Condensate Spill Volume(bbl): <u>0</u>
Estimated Flow Back Fluid Spill Volume(bbl): <u>0</u>	Estimated Produced Water Spill Volume(bbl): <u>&gt;=1 and &lt;5</u>
Estimated Other E&P Waste Spill Volume(bbl): <u>0</u>	Estimated Drilling Fluid Spill Volume(bbl): <u>0</u>

Specify: \_\_\_\_\_

#### Land Use:

Current Land Use: NON-CROP LAND Other(Specify): \_\_\_\_\_  
Weather Condition: Warm sunny  
Surface Owner: FEE Other(Specify): \_\_\_\_\_

#### Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State  Residence/Occupied Structure  Livestock  Public Byway  Surface Water Supply Area   
As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

We had a spill that was found yesterday 11-24-17 on the Wharton 33-32 well site (API# 05-071-06296). Lease operator reported a broken fitting on the well head allowed produced water to be spilled on location. The leak was isolated upon discovery, plans for repairs are being made. It is estimated at this time that 2bbls of produced water were spilled with no State Waters involved. Most of the water remained on location and a small amount ran off toward the lease road about 10'.

**List Agencies and Other Parties Notified:**

**OTHER NOTIFICATIONS**

Date	Agency/Party	Contact	Phone	Response
11/25/2017	COGCC	Jason Kosola	-	email
11/25/2017	LACOG	Bob Lucero	-	email
11/24/2017	Land owner	Gary James	-	Voice mail

**SPILL/RELEASE DETAIL REPORTS**

#1 Supplemental Report Date: 11/29/2017

FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	0	0	<input type="checkbox"/>
CONDENSATE	0	0	<input type="checkbox"/>
PRODUCED WATER	2	0	<input type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>

specify: \_\_\_\_\_

Was spill/release completely contained within berms or secondary containment? NO Was an Emergency Pit constructed? NO

*Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

**A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit**

Impacted Media (Check all that apply)  Soil  Groundwater  Surface Water  Dry Drainage Feature

Surface Area Impacted: Length of Impact (feet): 60 Width of Impact (feet): 3

Depth of Impact (feet BGS): 0 Depth of Impact (inches BGS): 0

How was extent determined?

Visual inspection

Soil/Geology Description:

From the NRCS soil survey map: Trujillo sandy loam

Depth to Groundwater (feet BGS) 50 Number Water Wells within 1/2 mile radius: 6

If less than 1 mile, distance in feet to nearest

Water Well	<u>240</u>	None <input type="checkbox"/>	Surface Water	<u>150</u>	None <input type="checkbox"/>
Wetlands		None <input checked="" type="checkbox"/>	Springs	<u>922</u>	None <input type="checkbox"/>
Livestock		None <input checked="" type="checkbox"/>	Occupied Building	<u>630</u>	None <input type="checkbox"/>

Additional Spill Details Not Provided Above:

During the investigation it was determined that vibration caused the nipple a nipple on the well head to break

### CORRECTIVE ACTIONS

#1 Supplemental Report Date: 11/29/2017

Cause of Spill (Check all that apply)  Human Error  Equipment Failure  Historical-Unknown  
 Other (specify) \_\_\_\_\_

Describe Incident & Root Cause (include specific equipment and point of failure)

The Root Cause was determined as mechanical failure due to excessive wear and tear.

Describe measures taken to prevent the problem(s) from reoccurring:

A work order was issued to have additional bracing added to the well head to eliminate the vibration.

Volume of Soil Excavated (cubic yards): \_\_\_\_\_

Disposition of Excavated Soil (attach documentation)  Offsite Disposal  Onsite Treatment  
 Other (specify) \_\_\_\_\_

Volume of Impacted Ground Water Removed (bbls): \_\_\_\_\_

Volume of Impacted Surface Water Removed (bbls): \_\_\_\_\_

### REQUEST FOR CLOSURE

**Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.**

Basis for Closure:  Corrective Actions Completed (documentation attached)  
 Work proceeding under an approved Form 27  
Form 27 Remediation Project No: \_\_\_\_\_

### OPERATOR COMMENTS:

Produced water quality data from the well associated with or representative of the spill is attached. Pioneer and its consulting geochemical specialists have found, after 20 years operating in the Raton Basin CBM field, that soil sampling no longer adds useful data on smaller, short-term spills as land uses and the environment are not sensitive to short-term exposure to CBM produced water. Effects to soil chemistry from short-term CBM produced water spills are temporary and shallow for several reasons: the water does not contain crude oil or liquid hydrocarbons; the TDS is significantly less than 10,000 mg/L; it is suitable for livestock watering, wildlife and in many cases surface discharge. Mixed with other water it is suitable for irrigation without impact.

When requested by the agency or landowner Pioneer has and will collect soil samples.  
Pioneer Natural Resources request closure of this spill based on this statement and attached water quality data.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: James Roybal  
Title: Environmental Supervisor Date: 11/29/2017 Email: james.roybal@pxd.com

COA Type	Description

### Attachment Check List

**Att Doc Num**      **Name**

401470216	ANALYTICAL RESULTS
-----------	--------------------

Total Attach: 1 Files

**General Comments**

**User Group**      **Comment**

**Comment Date**

		Stamp Upon Approval
--	--	------------------------

Total: 0 comment(s)