

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401481257
Date Received:
12/11/2017

FIR RESOLUTION FORM

CA Summary:
1 of 1 CAs from the FIR responded to on this Form
1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10071
Name of Operator: BARRETT CORPORATION* BILL
Address: 1099 18TH ST STE 2300
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name Phone Email
Doug Dennison 970-270-2853 ddennison@billbarrettcorp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682402345
Inspection Date: 06/28/2017 FIR Submit Date: 06/28/2017 FIR Status:

Inspected Operator Information:

Company Name: BARRETT CORPORATION* BILL Company Number: 10071
Address: 1099 18TH ST STE 2300
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 323189

Location Name: LOVELY-66N66W Number: 9SESW County: WELD
Qtrqr: SESW Sec: 9 Twp: 6N Range: 66W Meridian: 6
Latitude: 40.497290 Longitude: -104.785370

FACILITY - API Number: 05-123-00 Facility ID: 244889

Facility Name: LOVELY Number: 1
Qtrqr: SESW Sec: 9 Twp: 6N Range: 66W Meridian: 6
Latitude: 40.497290 Longitude: -104.785370

CORRECTIVE ACTIONS:

1 CA# 84078

Corrective Action: Remove culverts and perform reclamation in accordance to COGCC 1000 series reclamation rules at the battery location. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until Final Reclamation has passed. The prime time frame for a spring 2017 seeding has passed, to take advantage of a fall seeding, revegetation activities shall be complete no later than 11/15/2017.

Date: 11/15/2017

Response: CA COMPLETED Date of Completion: 12/08/2017

Operator Comment: BBC has had difficulty contacting the absentee surface owner to discuss plans for reclaiming the former tank-battery location and recently sent the surface owner a certified letter outlining plans for reclaiming the area. Pending either contact with the landowner or documentation that the letter was delivered, BBC will proceed with removing the remaining road base, hauling in topsoil, and reseeding the area. Timing for completion of this work is weather dependent but will be completed by 4/30/18.

COGCC Decision: **Not Approved**

COGCC Representative: This is an acknowledgement that the document was received. Operator has failed to perform reclamation activities per Rule 1004.a. and has failed to perform the required work per the previous corrective action inspection. Operator is over three (3) years out of compliance with Rule 1004.a. This issue may be forwarded onto Enforcement for further review.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Matt Barber Signed: _____

Title: Sr. Permit Analyst Date: 12/11/2017 8:38:37 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401481257	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files