

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/15/2017

Submitted Date:

12/19/2017

Document Number:

682600408**FIELD INSPECTION FORM**Loc ID 451507 Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10412Name of Operator: AUSCO PETROLEUM INCAddress: 113 N SANTA FE AVENUECity: FLORENCE State: CO Zip: 81226**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Goss, Aaron	303-495-0327	agoss@fremontpetroleum.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451506	WELL	DG	08/25/2017		043-06230	Bird 13-18	EI

General Comment:

Form 1A for operator appears to contain incorrect email addresses for designated agents. Operator shall update Form 1A with correct information.

Netting on open tank is inadequate.

Spill within secondary containment of fuel tanks.

Operator shall contact COGCC EPS arthur.koepsell@state.co.us to ensure compliance with Rule 609.

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
Other		>= 5 bbls		
Comment: Secondary containment around fuel tank is approximately half full of water/hydrocarbon. The spill is contained entirely within secondary containment and is not a high enough volume to be reportable under Rule 906.				
Corrective Action: Remove free fluids from secondary containment.				Date: 12/20/2017

In Containment: Yes

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1		Open Top		,
Comment: Netting on open tanks inadequate. Wildlife protections devices not adequate					
Corrective Action: Install or repair wildlife protection equipment					Date: 12/29/2017

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected FacilitiesFacility ID: 451506 Type: WELL API Number: 043-06230 Status: DG Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401491400	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4331151
682600410	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4331146