

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401499180  
Date Received:  
01/02/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

| Contact Name        | Phone | Email                      |
|---------------------|-------|----------------------------|
| <u>Beebe, Sabre</u> |       | <u>Sabre.Beebe@bp.com</u>  |
| <u>-</u>            |       | <u>SanJuanCOGCC@bp.com</u> |

COGCC INSPECTION SUMMARY:

FIR Document Number: 680602257  
Inspection Date: 11/08/2017 FIR Submit Date: 11/28/2017 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 326149

Location Name: TALIAFERRO TRUST GU A-N34N7W Number: 1NWSE County: LA PLATA  
Qtrqr: NWSE Sec: 1 Twp: 34N Range: 7W Meridian: N  
Latitude: 37.240984 Longitude: -107.584104

FACILITY - API Number: 05-067-00 Facility ID: 215950

Facility Name: Taliaferro Trust A Number: 1  
Qtrqr: NWSE Sec: 1 Twp: 34N Range: 7W Meridian: N  
Latitude: 37.240984 Longitude: -107.584104

CORRECTIVE ACTIONS:

1 CA# 112190

Corrective Action: Control weeds at the appropriate time but no later than June 15, 2018. Date: 06/15/2018

Response: CA COMPLETED Date of Completion: 12/19/2017

Operator Comment: Location has been placed on high priority treatment list for weed control in the spring of 2018.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**2** CA# 112191

Corrective Action: Install stormwater controls to stabilize erosion in the western project area. Care should be taken to avoid damage to existing vegetation, if damage occurs, disturbed areas will need seeding.

Date: 12/30/2017

Response: CA COMPLETED

Date of Completion: 12/19/2017

Operator Comment: Storm water BMP's have been installed in the erosion channels identified in the inspection. A rock rundown has been installed along with rock check dams see attached photos.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: This location has been placed on the priority list for weed treatment in 2018 and storm water BMP's have been installed see attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: \_\_\_\_\_

Title: Construction Specialist

Date: 1/2/2018 7:46:20 AM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

|           |                                |
|-----------|--------------------------------|
| 401499181 | Work completed photos attached |
|-----------|--------------------------------|

Total Attach: 1 Files