

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/02/2018

Submitted Date:

01/02/2018

Document Number:

684904816**FIELD INSPECTION FORM**Loc ID 452048 Inspector Name: Pesicka, Conor On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10518Name of Operator: CONFLUENCE DJ LLCAddress: 1001 17TH STREET #1250City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
Dickinson, Mike		mdickinson@confluencelp.com	Sr. VP of Operations

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
452352	WELL	DG	11/01/2017		123-45542	Buford 33-10-4L	DG

General Comment:

Inspected FacilitiesFacility ID: 452352 Type: WELL API Number: 123-45542 Status: DG Insp. Status: DG**Complaint**Comment: [Complaint #: 200444988](#)[Field Inspector Assigned: C Pesicka](#)[Well Number: 05- Location #: 452048](#)[Inspection Document #: 684904816](#)[Nature of complaint: Sound](#)[If Sound GPS Coordinates of Survey Location: n/a](#)[Inspection Observations:](#)[An inspection of the above site was conducted with a focus on sound and odor. Wind speed was >5 mph per anemometer. Will attempt in future.](#)

Corrective Action:

Date: