

FORM 5A Rev 06/12

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Table with columns DE, ET, OE, ES

Document Number: 401513313

Date Received:

COMPLETED INTERVAL REPORT

The completed interval Report, Form 5A, shall be submitted within thirty (30) days of completing a formation (successful or not), when a formation is temporarily abandoned or permanently abandoned, for a recompletion, reperforation or restimulation, or when a formation is commingled. Fill out a section for each formation. Attach as many pages as required to fully describe the work. List in order of completion.

1. OGCC Operator Number: 96850 2. Name of Operator: TEP ROCKY MOUNTAIN LLC 3. Address: PO BOX 370 City: PARACHUTE State: CO Zip: 81635 4. Contact Name: Kellye Garcia Phone: (832) 726-1159 Fax: Email: kgarcia@terraep.com

5. API Number 05-045-23428-00 6. County: GARFIELD 7. Well Name: Youberg Well Number: SR 322-12 8. Location: QtrQtr: SWNE Section: 12 Township: 7S Range: 94W Meridian: 6 9. Field Name: RULISON Field Code: 75400

Completed Interval

FORMATION: WILLIAMS FORK - CAMEO Status: PRODUCING Treatment Type: FRACTURE STIMULATION

Treatment Date: 12/07/2017 End Date: 12/13/2017 Date of First Production this formation: 12/26/2017 Perforations Top: 7266 Bottom: 9247 No. Holes: 240 Hole size: 35/100

Provide a brief summary of the formation treatment: Open Hole: 58867 bbls of slickwater; 1136850 100/Mesh; 1153 gals of biocide

This formation is commingled with another formation: Yes No Total fluid used in treatment (bbl): 58906 Max pressure during treatment (psi): 8169 Total gas used in treatment (mcf): Fluid density at initial fracture (lbs/gal): 8.43 Type of gas used in treatment: Min frac gradient (psi/ft): 0.74 Total acid used in treatment (bbl): Number of staged intervals: 10 Recycled water used in treatment (bbl): 58867 Flowback volume recovered (bbl): 14277 Fresh water used in treatment (bbl): Disposition method for flowback: RECYCLE Total proppant used (lbs): 1136850 Rule 805 green completion techniques were utilized: Reason why green completion not utilized:

Fracture stimulations must be reported on FracFocus.org

Test Information:

Date: 01/02/2018 Hours: 24 Bbl oil: 0 Mcf Gas: 1389 Bbl H2O: 0 Calculated 24 hour rate: Bbl oil: 0 Mcf Gas: 1389 Bbl H2O: 0 GOR: 0 Test Method: FLOWING Casing PSI: 2100 Tubing PSI: 1825 Choke Size: 18/64 Gas Disposition: SOLD Gas Type: DRY Btu Gas: 1086 API Gravity Oil: 0 Tubing Size: 2 + 3/8 Tubing Setting Depth: 9058 Tbg setting date: 12/19/2017 Packer Depth:

Reason for Non-Production: Date formation Abandoned: Squeeze: Yes No If yes, number of sacks cmt \*\* Bridge Plug Depth: \*\* Sacks cement on top: \*\* Wireline and Cement Job Summary must be attached.

Comment:

Completion operations for this well were delayed for an extended amount of time, and the well was placed on a deferred list. Please reference the Form 5 and attached correspondence letter.

The actual TPZ footages for the SR 322-12 are 1714 FNL & 1868 FWL.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Kellye Garcia

Title: Land & Regulatory Tech Date: \_\_\_\_\_ Email kgarcia@terraep.com  
:

### Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
401513320	WIRELINE JOB SUMMARY
401513321	OTHER

Total Attach: 2 Files

### General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)