



STATE OF
COLORADO

EnviroScan - DNR, OGCC <dnr_ogcc.enviroscan@state.co.us>

Fwd: 401505457_approved Chevron Rangely January 6 2017 168 bbl spill

1 message

Neidel - DNR, Kris <kris.neidel@state.co.us>

Wed, Jan 10, 2018 at 11:17 AM

To: "EnviroScan - DNR, OGCC" <dnr_ogcc.enviroscan@state.co.us>

Cc: Alex Fischer <alex.fischer@state.co.us>, Mark Schlagenhauf - DNR <mark.schlagenhauf@state.co.us>

Document Name(s)	please upload this email as "root cause request" to below facility number	
Document Number	<i>(leave blank if not already assigned)</i>	
Date Received		
Is data entry needed?	NO	
Indexing Information	Unique ID Type	Unique ID Number
First	Remediation (REM)	
Second	Facility ID (FAC)	453683
Third*	NOAV	
Additional Instructions		

Kris Neidel
Environmental Protection Specialist Northwest Area
Colorado Oil and Gas Conservation Commission
Office [970-871-1963](tel:970-871-1963)
Cell [970-846-5097](tel:970-846-5097)



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

----- Forwarded message -----

From: **Schlagenhauf - DNR, Mark** <mark.schlagenhauf@state.co.us>

Date: Wed, Jan 10, 2018 at 10:29 AM

Subject: 401505457_approved Chevron Rangely January 6 2017 168 bbl spill

To: bkleinsa@chevron.com

Cc: "Moschetti, Nick (NMOS)" <nmos@chevron.com>, Alex Fischer - DNR <alex.fischer@state.co.us>, "Neidel - DNR, Kris" <kris.neidel@state.co.us>

Ben,

In the form 19 subsequent, please submit information concerning root cause of the failure and explain the actions that will be taken to prevent reoccurrence.

Thank you.

Regards,

Mark Schlagenhauf P.E.
Engineering Integrity Supervisor
COGCC
[303-894-2100](tel:303-894-2100) x 5177



401505457_approved Chevron Rangely January 6 2017 spill.pdf
101K