

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401513201  
Date Received:  
01/15/2018

## FIR RESOLUTION FORM

### CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10412  
Name of Operator: AUSCO PETROLEUM INC  
Address: 113 N SANTA FE AVENUE  
City: FLORENCE State: CO Zip: 81226  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name	Phone	Email
Goss, Aaron	303-495-0327	agoss@fremontpetroleum.com
Axelson, John		john.axelson@state.co.us

### COGCC INSPECTION SUMMARY:

FIR Document Number: 682600436  
Inspection Date: 01/09/2018 FIR Submit Date: 01/10/2018 FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: AUSCO PETROLEUM INC Company Number: 10412  
Address: 113 N SANTA FE AVENUE  
City: FLORENCE State: CO Zip: 81226

### LOCATION - Location ID: 439367

Location Name: Pathfinder C-18 Number: 8 County: FREMONT  
Qtrqr: NWNE Sec: 18 Twp: 20S Range: 69W Meridian: 6  
Latitude: 38.314773 Longitude: -105.150555

### FACILITY - API Number: 05-043-00 Facility ID: 439366

Facility Name: Columbus Number: 1  
Qtrqr: NWNE Sec: 18 Twp: 20S Range: 69W Meridian: 6  
Latitude: 38.314773 Longitude: -105.150555

### CORRECTIVE ACTIONS:

1 ☒ CA# 113825

Corrective Action: Net or fence pit to prevent access per rule 902.d. Date: 01/12/2018

Response: CA COMPLETED Date of Completion: 01/11/2018

Operator Comment: Operator place plywood over section of Pit fence that did not have netting coverage. Operator secured plywood to fence. No additional access points present at this time. Operator attached photo of repair work.

COGCC Decision: Approved

COGCC Representative: Attached photos show compliance with Corrective Action.

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Operator place plywood over section of Pit fence that did not have netting coverage. Operator secured plywood to fence. No additional access points present at this time. Operator attached photo of repair work.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Aaron J Goss

Signed: \_\_\_\_\_

Title: Executive V.P.

Date: 1/15/2018 9:48:58 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
401513201	FIR RESOLUTION SUBMITTED
401513208	Columbis Pit Netting Repair

Total Attach: 2 Files