

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401516727

Date Received:

01/18/2018

Spill report taken by:

Spill/Release Point ID:

SPILL/RELEASE REPORT (INITIAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC	Operator No: 10112	Phone Numbers
Address: 5057 KELLER SPRINGS RD STE 650		Phone: (303) 244-8114
City: ADDISON State: TX Zip: 75001		Mobile: (720) 2572302
Contact Person: Alyssa Beard		Email: regulatory@foundationenergy.com

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 401516727

Initial Report Date: 01/17/2018 Date of Discovery: 01/17/2018 Spill Type: Recent Spill

Spill/Release Point Location:

Location of Spill/Release: QTRQTR Lot 4 SEC 6 TWP 7N RNG 59W MERIDIAN 6

Latitude: 40.611190 Longitude: -104.025991

Municipality (if within municipal boundaries): County: WELD

Reference Location:

Facility Type: TANK BATTERY Facility/Location ID No 435380
 No Existing Facility or Location ID No.
 Well API No. (Only if the reference facility is well) 05- -

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? No

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): >=1 and <5 Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0 Estimated Produced Water Spill Volume(bbl): 0

Estimated Other E&P Waste Spill Volume(bbl): 0 Estimated Drilling Fluid Spill Volume(bbl): 0

Specify:

Land Use:

Current Land Use: NON-CROP LAND Other(Specify):

Weather Condition: Sunny

Surface Owner: FEE Other(Specify):

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State Residence/Occupied Structure Livestock Public Byway Surface Water Supply Area
As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

The release was caused by over-pressuring of the fire tube gasket on the treater. The well was immediately shut in and pressure was removed from the treater vessel. A vac truck removed remaining fluids from the treater and removed standing oil from the ground.

List Agencies and Other Parties Notified:

OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
1/18/2018	Weld County LEPC	Roy Rudisill	-	Emailed release information
1/18/2018	Landowner	Don Wickstrom	970-6563676	Left voicemail with release information
1/18/2018	COGCC	Rick Allison	970-4612970	Notified Rick of release in a phone call

OPERATOR COMMENTS:

--

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Alyssa Beard

Title: EHS and Regulatory Date: 01/18/2018 Email: regulatory@foundationenergy.com

COA Type

Description

--	--

Attachment Check List

Att Doc Num

Name

401518456	TOPOGRAPHIC MAP
-----------	-----------------

Total Attach: 1 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)