

FORM 5A

Rev 06/12

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Table with columns DE, ET, OE, ES

Document Number: 401518050

Date Received: 01/18/2018

COMPLETED INTERVAL REPORT

The completed interval Report, Form 5A, shall be submitted within thirty (30) days of completing a formation (successful or not), when a formation is temporarily abandoned or permanently abandoned, for a recompletion, reperforation or restimulation, or when a formation is commingled. Fill out a section for each formation. Attach as many pages as required to fully describe the work. List in order of completion.

1. OGCC Operator Number: 96850
2. Name of Operator: TEP ROCKY MOUNTAIN LLC
3. Address: PO BOX 370 City: PARACHUTE State: CO Zip: 81635
4. Contact Name: Kellye Garcia Phone: (832) 726-1159 Fax: Email: kgarcia@terraep.com

5. API Number 05-045-23432-00
6. County: GARFIELD
7. Well Name: Youberg Well Number: SR 541-12
8. Location: QtrQtr: SWNE Section: 12 Township: 7S Range: 94W Meridian: 6
9. Field Name: RULISON Field Code: 75400

Completed Interval

FORMATION: WILLIAMS FORK - CAMEO Status: PRODUCING Treatment Type: FRACTURE STIMULATION

Treatment Date: 12/07/2017 End Date: 12/14/2017 Date of First Production this formation: 12/26/2017

Perforations Top: 7403 Bottom: 9388 No. Holes: 240 Hole size: 35/100

Provide a brief summary of the formation treatment: Open Hole: []

50758 bbls of slickwater; 992200 100/Mesh; 1058 gals of biocide

This formation is commingled with another formation: [] Yes [X] No

Total fluid used in treatment (bbl): 50783 Max pressure during treatment (psi): 7094
Total gas used in treatment (mcf): Fluid density at initial fracture (lbs/gal): 8.43
Type of gas used in treatment: Min frac gradient (psi/ft): 0.68
Total acid used in treatment (bbl): Number of staged intervals: 10
Recycled water used in treatment (bbl): 50758 Flowback volume recovered (bbl): 11060
Fresh water used in treatment (bbl): Disposition method for flowback: RECYCLE
Total proppant used (lbs): 992200 Rule 805 green completion techniques were utilized: [X]

Reason why green completion not utilized:

Fracture stimulations must be reported on FracFocus.org

Test Information:

Date: 12/30/2017 Hours: 24 Bbl oil: 0 Mcf Gas: 1304 Bbl H2O: 0
Calculated 24 hour rate: Bbl oil: 0 Mcf Gas: 1304 Bbl H2O: 0 GOR: 0
Test Method: FLOWING Casing PSI: 1752 Tubing PSI: 1513 Choke Size: 18/64
Gas Disposition: SOLD Gas Type: DRY Btu Gas: 1079 API Gravity Oil: 0
Tubing Size: 2 + 3/8 Tubing Setting Depth: 9187 Tbg setting date: 12/20/2017 Packer Depth:

Reason for Non-Production:

Date formation Abandoned: Squeeze: [] Yes [] No If yes, number of sacks cmt

** Bridge Plug Depth: ** Sacks cement on top: ** Wireline and Cement Job Summary must be attached.

Comment:

Completion operations for this well were delayed for an extended amount of time, and the well was placed on a deferred list. Please reference the Form 5 and attached correspondence letter.

The actual TPZ footages for the SR 541-12 are 1208 FNL & 646 FEL.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Kellye Garcia

Title: Land & Regulatory Tech Date: 1/18/2018 Email kgarcia@terraep.com
:

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
401518050	FORM 5A SUBMITTED
401518058	WELLBORE DIAGRAM
401518059	OTHER

Total Attach: 3 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Agency	Corrected min frac gradient via email from Kellye	01/23/2018

Total: 1 comment(s)