

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401521640
Date Received:
01/22/2018

FIR RESOLUTION FORM

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Lindsey Rider

970-285-2711

lrider@caerusoilandgas.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680102524

Inspection Date: 12/20/2017

FIR Submit Date: 01/02/2018

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 423633

Location Name: KM Number: C08 799 County: _____

Qtrqtr: NENW Sec: 8 Twp: 7S Range: 99W Meridian: 6

Latitude: 39.465672 Longitude: -108.466519

FACILITY - API Number: 05-045-00 Facility ID: 423633

Facility Name: KM Number: C08 799

Qtrqtr: NENW Sec: 8 Twp: 7S Range: 99W Meridian: 6

Latitude: 39.465672 Longitude: -108.466519

CORRECTIVE ACTIONS:

1 ☒ CA# 113662

Corrective Action: Close / Backfill Open Rat Hole. Refer to Photo log attached.

Date: 02/02/2018

Response: CA COMPLETED

Date of Completion: 01/12/2018

Operator Comment: Rat hole backfilled.

COGCC Decision: Approved pending re-inspection

COGCC
Representative: _____

2 ☒ CA# 113663

Corrective Action: Reclaim Location for Interim Reclamation per COGCC 1003 Series Rules; installing Reclamation in areas no longer needed for Use, Production, Drilling or Subsequent Operations. Reclamation Activities should be complete by 6/1/2018.

Date: 06/01/2018

Response: CA COMPLETED

Date of Completion: 01/22/2018

Operator Comment: Additional Interim Reclamation is planned for the spring of 2018.

COGCC Decision: Approved pending re-inspection

COGCC
Representative: _____

3 ☒ CA# 113664

Corrective Action: Reinstall or Remove Wattles at base of Fill slope that have become Debris. Removal of Wattles embedded in Frozen ground may be delayed until ground conditions permit.

Date: 02/02/2018

Response: CA COMPLETED

Date of Completion: 01/12/2018

Operator Comment: Wattles removed.

COGCC Decision: Approved pending re-inspection

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lindsey Rider

Signed: _____

Title: EHS Lead

Date: 1/22/2018 12:12:57 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401521640	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files