

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/02/2018

Submitted Date:

02/05/2018

Document Number:

690100364**FIELD INSPECTION FORM**Loc ID 320426 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10454Name of Operator: PETROSHARE CORPORATIONAddress: 9635 MAROON CIRCLE #400City: ENGLEWOOD State: CO Zip: 80112**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Powell, Harold	(918)-774-3120	hpowell@petrosharecorp.com	
Lloyd, Bill		blloyd@petrosharecorp.com	
Brown, Devin		dbrown@petrosharecorp.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203732	WELL	SI	04/01/2017	GW	001-09292	WYMAN 34-6	EG

General Comment:[Photos uploaded can be accessed via link\(s\) at end of report.](#)

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	(2) unused unmarked flowline risers observed in the area of the horizontal separator; (1) 2" carbon steel riser near the inlet to the separator and (1) 2" carbon steel riser surrounded by fencing approximately 35' NW of the separator.		
Corrective Action:	Comply with rule 603.f. For unused unmarked flowline risers 24hrs to lock out/ tag out; 30 days to remove unused risers.		Date: 03/05/2018

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 203732 Type: WELL API Number: 001-09292 Status: SI Insp. Status: EG**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: COGCC Form 6 notice of intent to abandon doc #401400097 received on 01/05/2018.
 Wellhead valves are currently locked/ tagged out. No flowline available at wellhead.
 Disconnected equipment on location is considered unused equipment; COGCC rule
 603.f. 90 days to remove unused equipment when machinery is required for removal.

Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401535918	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4370552
690100371	Wellhead and signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4370549
690100372	Unused flowline riser at horizontal separator	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4370550
690100373	Unused unmarked flowline riser NW of separator	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4370551