

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401557349

Date Received:

02/27/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Brian Dodek

Phone

7204406100

Email

BDodek@bonanzacrk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682403207

Inspection Date: 01/12/2018

FIR Submit Date: 01/19/2018

FIR Status: _____

Inspected Operator Information:

Company Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Company Number: 8960

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 438730

Location Name: State Pronghorn Number: V-32 Pad County: _____

Qtrqr: NENE Sec: 32 Twp: 5N Range: 61W Meridian: 6

Latitude: 40.361060 Longitude: -104.225190

FACILITY - API Number: 05-123- -00 Facility ID: 438730

Facility Name: State Pronghorn Number: V-32 Pad

Qtrqr: NENE Sec: 32 Twp: 5N Range: 61W Meridian: 6

Latitude: 40.361060 Longitude: -104.225190

CORRECTIVE ACTIONS:

1 CA# 114139

Corrective Action: Comply with Rule 603.f. to control and manage weedy, annual vegetation to prevent weed debris and to prevent dispersing seeds onto adjacent lands.

Date: 02/02/2018

Response: CA COMPLETED

Date of Completion: 02/19/2018

Operator Comment: To comply with Rule 603.f the entire pad including the slopes have been mowed to manage weedy, annual vegetation. All of the loose tumbleweeds stuck in the perimeter fence were also removed. Please find the attached pictures for verification. Please note that this facility and well pad are totally surrounded by unmanaged land that is overgrown with tumbleweeds. This CA was completed once prior to the initial CA date and additional work was required and completed on 2/19/18.

COGCC Decision: _____

COGCC
Representative:

3 CA# 114141

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 02/16/2018

Response: CA COMPLETED

Date of Completion: 02/02/2018

Operator
Comment:

To comply with Rule 1002.f all of the accumulated material in the sediment trap was removed and the walls were redefined.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Brian Dodek

Signed: _____

Title: Env Manager

Date: 2/27/2018 4:18:03 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401557357	Pronghorn V-32 Images
-----------	-----------------------

Total Attach: 1 Files