

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401499180

Date Received:

01/02/2018

FIR RESOLUTION FORM

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Beebe, Sabre

Sabre.Beebe@bp.com

SanJuanCOGCC@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680602257

Inspection Date: 11/08/2017

FIR Submit Date: 11/28/2017

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 326149

Location Name: TALIAFERRO TRUST GU A- N34N7W Number: 1NWSE County: LA PLATA

Qtrqr: NWSE Sec: 1 Twp: 34N Range: 7W Meridian: N

Latitude: 37.240984 Longitude: -107.584104

FACILITY - API Number: 05-067- -00 Facility ID: 215950

Facility Name: Taliaferro Trust A Number: 1

Qtrqr: NWSE Sec: 1 Twp: 34N Range: 7W Meridian: N

Latitude: 37.240984 Longitude: -107.584104

CORRECTIVE ACTIONS:

1 ☒ CA# 112190

Corrective Action: Control weeds at the appropriate time but no later than June 15, 2018.

Date: 06/15/2018

Response: CA COMPLETED

Date of Completion: 12/19/2017

Operator
Comment:

Location has been placed on high priority treatment list for weed control in the spring of 2018.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 112191

Corrective Action: Install stormwater controls to stabilize erosion in the western project area. Care should be taken to avoid damage to existing vegetation, if damage occurs, disturbed areas will need seeding.

Date: 12/30/2017

Response: CA COMPLETED

Date of Completion: 12/19/2017

Operator Comment: Storm water BMP's have been installed in the erosion channels identified in the inspection. A rock rundown has been installed along with rock check dams see attached photos.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: This location has been placed on the priority list for weed treatment in 2018 and storm water BMP's have been installed see attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Construction Specialist

Date: 01/02/2018 7:46:20 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401499180	FIR RESOLUTION SUBMITTED
401499181	Work completed photos attached

Total Attach: 2 Files