

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401510159
Date Received:
01/11/2018

FIR RESOLUTION FORM

CA Summary:
1 of 1 CAs from the FIR responded to on this Form
1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Beebe, Sabre		Sabre.Beebe@bp.com
.		SanJuanCOGCC@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680602305
Inspection Date: 11/29/2017 FIR Submit Date: 12/15/2017 FIR Status:

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 326600

Location Name: FEDERAL LAND BANK B- M34N9W Number: 25SWSW County: LA PLATA
Qtrqtr: SWS Sec: 25 Twp: 34N Range: 9W Meridian: M
Latitude: 37.155396 Longitude: -107.784267

FACILITY - API Number: 05-067-00 Facility ID: 258789

Facility Name: FEDERAL LAND BANK B Number: 2
Qtrqtr: SWS Sec: 25 Twp: 34N Range: 9W Meridian: M
Latitude: 37.155396 Longitude: -107.784267

CORRECTIVE ACTIIONS:

1 CA# 113431

Corrective Action: This is the second corrective action for weeds in the project area. Control infestation of knapweed within the project area. Initial corrective action date will remain to document time since original corrective action.

Date: 06/15/2017

Response: CA COMPLETED Date of Completion: 04/25/2017

In response to Inspection #680601453 dated as submitted 4/20/2017 BP dispatch the profession weed

Operator Comment: management contractor to location to manually remove the Russian Knapweed noted in the inspection as well as any other noxious weed species present at that point in time. See attached document of manual removal photos dated 4/25/17. In addition the Federal Land Bank B 2 location interim reclamation area was treated with herbicide on 6/30/17 and again on 9/1/17 for Russian Knapweed. This location is on the priority weed treatment list due to the presence of Russian Knapweed and will be treated 2 times each year in the spring and fall which is the recommendations. In consulting with professional weed control companies BP has been advised that control of Russian Knapweed is documented in research documents to take up to 3 years or longer to eradicate. The development of the priority list will assist in assuring treatment is appropriate, tracked and continued 2 times per year.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: In response to Inspection #680601453 dated as submitted 4/20/2017 BP dispatch the profession weed management contractor to location to manually remove the Russian Knapweed noted in the inspection as well as any other noxious weed species present at that point in time. See attached document of manual removal photos dated 4/25/17. In addition the Federal Land Bank B 2 location interim reclamation area was treated with herbicide on 6/30/17 and again on 9/1/17 for Russian Knapweed. This location is on the priority weed treatment list due to the presence of Russian Knapweed and will be treated 2 times each year in the spring and fall which is the recommendations. In consulting with professional weed control companies BP has been advised that control of Russian Knapweed is documented in research documents to take up to 3 years or longer to eradicate. The development of the priority list will assist in assuring treatment is appropriate, tracked and continued 2 times per year.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Compliance Specialist

Date: 01/11/2018 9:05:53 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401510159	FIR RESOLUTION SUBMITTED
401510209	Weed removal photos 4/25/17

Total Attach: 2 Files