

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401557369

Date Received:

02/27/2018

FIR RESOLUTION FORM

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Brian Dodek

7204406100

BDodek@Bonanzacrk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682403215

Inspection Date: 01/12/2018

FIR Submit Date: 01/19/2018

FIR Status: _____

Inspected Operator Information:

Company Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Company Number: 8960

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 441121

Location Name: State Pronghorn Number: 44-32 Pad County: _____

Qtrqtr: SESE Sec: 32 Twp: 5N Range: 61W Meridian: 6

Latitude: 40.351040 Longitude: -104.227360

FACILITY - API Number: 05-123- -00 Facility ID: 441121

Facility Name: State Pronghorn Number: 44-32 Pad

Qtrqtr: SESE Sec: 32 Twp: 5N Range: 61W Meridian: 6

Latitude: 40.351040 Longitude: -104.227360

CORRECTIVE ACTIONS:

1 ☒ CA# 114142

Corrective Action: Comply with Rule 603.f. to control and manage weedy, annual vegetation to prevent weed debris and to prevent dispersing seeds onto adjacent lands.

Date: 02/02/2018

Response: CA COMPLETED

Date of Completion: 02/19/2018

Operator
Comment:

To comply with Rule 603.f the entire pad including the slopes have been mowed to manage weedy, annual vegetation. All of the loose tumbleweeds stuck in the perimeter fence were also removed. Please find the attached pictures for verification. Please note that this facility and well pad are totally surrounded by unmanaged land that is overgrown with tumbleweeds. This CA was completed once prior to the initial CA date and additional work was required and completed on 2/19/18.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

Staff would like to address two comments submitted by the Operator:

#1- Staff does not agree with the following statement provided by the Operator "Please note that this facility and well pad are totally surrounded by unmanaged land that is overgrown with tumbleweeds."

Referring to Inspection Photo Document #682403216, submitted 1/19/18, Photos 5 and 7-9 do not indicate reference areas are totally surrounded by unmanaged land. Staffs inspection photos would indicate reference areas consists mainly of Prairie sandreed (*Calamovilfa longifolia*) and Sand sagebrush (*Artemisia filifolia*).

#2- Staff does not agree with the following statement provided by the Operator "This CA was completed once prior to the initial CA date and additional work was required and completed on 2/19/18."

Operator did not fully complete the corrective action to control and manage weedy, annual vegetation by the initial CA date. Re-inspection Document # 682403314, noted the following: Appears the Operator mowed Russian thistle but weed debris remains in the perimeter fences. Operator has not fully performed the corrective actions; therefore, the corrective actions remain open until resolved.

3 ☒ CA# 114144

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 02/16/2018

Response: CA COMPLETED

Date of Completion: 02/02/2018

Operator Comment: To comply with Rule 1002.f the unconsolidated soil around the rock channel was compacted to prevent erosion. All of the accumulated sediment in the sediment trap was removed and the walls were redefined.

COGCC Decision: Approved pending re-inspection

COGCC Representative: pproved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Brian Dodek

Signed: _____

Title: Env Manager

Date: 2/27/2018 4:19:26 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401557369	FIR RESOLUTION SUBMITTED
-----------	--------------------------

401557382	Pronghorn 44-32 Images
-----------	------------------------

Total Attach: 2 Files