

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401302931
Date Received:
06/07/2017

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10110
Name of Operator: GREAT WESTERN OPERATING COMPANY LLC
Address: 1801 BROADWAY #500
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
<u>Kraich, Adam</u>		<u>akraich@adcogov.org</u>
<u>Adamczyk, Megan</u>		<u>megan.adamczyk@state.co.us</u>
<u>Scot Donato</u>		<u>cogccinspections@gwogco.com</u>
<u>Ash, Margaret</u>		<u>margaret.ash@state.co.us</u>
<u>Mah, Steven</u>		<u>steven.mah@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 684903823
Inspection Date: 06/05/2017 FIR Submit Date: 06/06/2017 FIR Status:

Inspected Operator Information:

Company Name: GREAT WESTERN OPERATING COMPANY LLC Company Number: 10110
Address: 1801 BROADWAY #500
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 449174

Location Name: Ocho LD PAD Number: 17-379HN County:
Qtrqtr: NENW Sec: 8 Twp: 1S Range: 67W Meridian: 6
Latitude: 39.984583 Longitude: -104.914033

FACILITY - API Number: 05-001-00 Facility ID: 449174

Facility Name: Ocho LD PAD Number: 17-379HN
Qtrqtr: NENW Sec: 8 Twp: 1S Range: 67W Meridian: 6
Latitude: 39.984583 Longitude: -104.914033

CORRECTIVE ACTIIONS:

1 CA# 80670

Corrective Action: Clean out vehicle tracking BMPs on the oil and gas location. If material is tracked onto County or public roads, contact the appropriate authority to address that road.

Date: 06/08/2017

Response: CA COMPLETED

Date of Completion: 06/06/2017

Operator Comment: Received complaint notification and inspection Form from COGCC at 8 am on 6-6-17. Inspection claims failed sediment tracking system and sediments on road Hwy 7. Hwy 7 was swept/vacuumed on 6-6-17 and the tracking pad on Ocho Pad exit was replaced. See attached photos of both. Great Western does not own or control Monaco Street to the east of Ocho Pad where the pad exits. Monaco Street is not part of our Surface Use Agreement access with the landowner. Thus, we are unable to install BMPs on this road. We will continue to ensure th tracking pad is functioning properly and that any sediment from Monaco Street on Hwy 7 is cleaned up in a timely manner.

COGCC Decision: **Not Approved**

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Laura Harter Signed: _____

Title: Production Tech Date: 6/7/2017 2:32:21 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401302931	FIR RESOLUTION SUBMITTED
401303016	Ocho Road Photo
401303019	Ocho Road Photo 2

Total Attach: 3 Files