



SURFACE CASING CHECK

Well Name CE221 41-26 123-23101

New Drill  Refiling  Deepen  Re-Enter  Recomplete and Operate  Plug and Abandon  Casing Repair

SB5 Base of Fox Hills 355' + 50' = 405'

Cheyenne Basin Map Base of Fox Hills \_\_\_\_\_

Fox Hills Protection Area 5% Rule \_\_\_\_\_

Deepest Water Well w/in One Mile 69' + 50' = 119'

Operator-Proposed Surface Casing Depth \_\_\_\_\_

Actual Surface Casing Depth 410'

Change Permit Surface Casing Depth from \_\_\_\_\_ to \_\_\_\_\_

OK on  this well's or  offset well's induction log at \_\_\_\_\_