

Well Name:	Terrill 1-15	API #	05-067-06549
Inspection Number:	680602468		
Corrective Action:	Storm water controls need to be Installed to stabilize erosion within and along the access road.		
Correction Action Due:	3/30/2018		
Action Completed:	3/7/2018		
Action Taken:	Installed a series of stone barriers along the access road.		



Action Taken: Cleaned out access road cut outs.

