

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401581998
Date Received:
03/21/2018

FIR RESOLUTION FORM

CA Summary:
2 of 2 CAs from the FIR responded to on this Form
2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10261
Name of Operator: BAYSWATER EXPLORATION & PRODUCTION LLC
Address: 730 17TH ST STE 500
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Blyth, Tom	(303) 893-2503	tblyth@bayswater.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 682403348
Inspection Date: 02/27/2018 FIR Submit Date: 03/01/2018 FIR Status:

Inspected Operator Information:

Company Name: BAYSWATER EXPLORATION & PRODUCTION LLC Company Number: 10261
Address: 730 17TH ST STE 500
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 419217

Location Name: G & D Hanks Number: 10-27 Pad County:
Qtrqtr: SWSE Sec: 27 Twp: 7N Range: 66W Meridian: 6
Latitude: 40.541630 Longitude: -104.761688

FACILITY - API Number: 05-123-00 Facility ID: 419217

Facility Name: G & D Hanks Number: 10-27 Pad
Qtrqtr: SWSE Sec: 27 Twp: 7N Range: 66W Meridian: 6
Latitude: 40.541630 Longitude: -104.761688

CORRECTIVE ACTIONS:

1 CA# 114637

Corrective Action: Perform reclamation in accordance to Rule 1003. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Use a seed mixture with species consistent with the adjacent plant community or a seed mixture requested by the surface owner. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until the location meets Rule 1003 standards. Interim reclamation activities shall be complete no later than April 30, 2018.

Date: 04/30/2018

Response: CA COMPLETED Date of Completion: 03/01/2018

Operator Comment: Site is no longer operated by Bayswater

COGCC Decision: Approved

COGCC Representative: Form 10 (Document # 401490807) Change of Operator is IN-PROCESS. PDC has taken responsibility and has already performed the corrective actions.

2 CA# 114638

Corrective Action: Install or repair required BMPs.

Date: 03/06/2018

Response: CA COMPLETED

Date of Completion: 03/01/2018

Operator Comment: Site is no longer operated by Bayswater.

COGCC Decision: Approved

COGCC Representative: Form 10 (Document # 401490807) Change of Operator is IN-PROCESS. PDC has taken responsibility and has already performed the corrective actions.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tom Blyth

Signed: _____

Title: Admin. Asst.

Date: 3/21/2018 2:08:48 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

401581998	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files