

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/23/2018

Submitted Date:

03/23/2018

Document Number:

688400039**FIELD INSPECTION FORM**

Loc ID 450069 Inspector Name: Gomez, Jason On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10651
 Name of Operator: VERDAD RESOURCES LLC
 Address: 5950 CEDAR SPRINGS ROAD
 City: DALLAS State: TX Zip: 75235

Findings:

- 2 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Beecherl, Arthur	214-838-2783	Regulatory@verdadoil.com	
Adamczyk, Megan		megan.adamczyk@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
450067	WELL	DG	05/17/2017		123-44624	HOMESTEAD 20	WO

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	LOCATION		
Comment:	Approx 32' sound walls on south and west and east end of location		
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 450067 Type: WELL API Number: 123-44624 Status: DG Insp. Status: WO

Complaint

Comment: **Field Inspector Assigned: Jason E. Gomez**

Complaint Received:

Date: 2-20-2018

Complaint Contacted:

Date: 2-23-2018 Time 1300 Hrs

Location #: 450069

Inspection Document #: 688400039

Nature of complaint: Noise/lights/odors

Field Inspector Actions:

On 2-20-2018, I was contacted by complaint specialist Megan Adamczyk in reference to some complaints received by the COGCC in reference to noise, lights and odors. The complaint stated the issues were occurring in the Brighton area originating from the Verdad, Homestead location.

On 2-23-2018, I attempted to make contact with the complaint she indicated in her complaint she was experiencing noise lighting and odor issues coming from the Verdad Homestead location. I performed a complete site inspection of the Verdad location. I reviewed location records, which did not show any abnormal fracking conditions at the time of the complaints. I reviewed third party sound records at the times of the complaint and at no time did the drilling operation exceed COGCC rules according to the sound study information reviewed. I checked the area around the complaints residence at the time of the inspection I did not detect any odors at the time. At the time of the inspection all lighting appeared to be [pointed down and toward the ground per COGCC rules.

No violation of COGCC rules were observed at the time of the inspection of the frack operation nor in the surrounding neighborhood.

All information reviewed and site inspection information were submitted to the complaint specialist for further review.

Corrective Action:

Date:

Well Stimulation

Stimulation Company: Halliburton Stimulation Type: HYDRAULIC FRAC

Other: _____

Observation:

Maximum Casing Recorded: _____ PSI

Tubing: _____

Surface: _____

Intermediate: _____

Production: _____

Instantaneous Shut-In Pressure (ISIP) _____

Bradenhead Psi: _____

Frac Flow Back: Fluid: _____ Gas: _____

Comment: _____

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Ditches	Pass	Covering Materials	Pass	
Gravel	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	
Compaction	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688400040	Sound study rresults	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4414457