

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401600703

Date Received:

04/09/2018

Spill report taken by:

LUJAN, CARLOS

Spill/Release Point ID:

454722

SPILL/RELEASE REPORT (INITIAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: <u>CAERUS PICEANCE LLC</u>	Operator No: <u>10456</u>	Phone Numbers
Address: <u>1001 17TH STREET #1600</u>		Phone: <u>(970) 285-9606</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>		Mobile: <u>(970) 778-2314</u>
Contact Person: <u>Jake Janicek</u>		Email: <u>jjanicek@caerusoilandgas.com</u>

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 401600703

Initial Report Date: 04/09/2018 Date of Discovery: 04/09/2018 Spill Type: Recent Spill

Spill/Release Point Location:

Location of Spill/Release: QTRQTR SESW SEC 17 TWP 8S RNG 96W MERIDIAN 6

Latitude: 39.344394 Longitude: -108.134166

Municipality (if within municipal boundaries): _____ County: MESA

Reference Location:

Facility Type: TANK BATTERY Facility/Location ID No 334066
 No Existing Facility or Location ID No.
 Well API No. (Only if the reference facility is well) 05- -

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0 Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0 Estimated Produced Water Spill Volume(bbl): >=5 and <100

Estimated Other E&P Waste Spill Volume(bbl): 0 Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: _____

Land Use:

Current Land Use: NON-CROP LAND Other(Specify): _____

Weather Condition: Cloudy, 75

Surface Owner: FEDERAL Other(Specify): _____

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State Residence/Occupied Structure Livestock Public Byway Surface Water Supply Area
As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

During routine tank gauging, the lease operator responsible for this location noticed fluid was missing from the southwestern most tank. Through hydrostatic testing, we confirmed there was a hole in the tank. The tank has since been removed from service. We then conducted a hydrostatic test on the secondary containment and confirmed a liner failure. It is believed the produced water missing from the southwestern most tank leaked out of the tank, through the liner, and into the soil beneath and around the secondary containment.

List Agencies and Other Parties Notified:

OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
4/9/2018	BLM	Carmia Wooley	970-876-9063	No response at time of reporting

OPERATOR COMMENTS:

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Jake Janicek
Title: EHS Lead Date: 04/09/2018 Email: jjanicek@caerusoilandgas.com

COA Type

Description

COA Type	Description

Attachment Check List

Att Doc Num

Name

Att Doc Num	Name
401600703	SPILL/RELEASE REPORT(INITIAL)

Total Attach: 1 Files

General Comments

User Group

Comment

Comment Date

Environmental	Sample and remediate soil underneath the liner where liner has been compromised. Replace or repair liner. Replace or repair leaking tank.	04/11/2018
Environmental	Assess nature and extent of contamination with confirmation soil samples. Remediate to Table 910-1 standards and provide documentation in a either a Supplemental F-19 if cleaned up immediately (or in a short period of time) or F-27 if extended remediation is required.	04/11/2018

Total: 2 comment(s)