

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/11/2018

Submitted Date:

04/18/2018

Document Number:

680303157**FIELD INSPECTION FORM**
 Loc ID 312202 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 88370Name of Operator: TIMKA RESOURCES LTDAddress: 2116 EAST HIGHWAY 402City: LOVELAND State: CO Zip: 80537**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Pivonka, Todd		pivonka2010@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
219441	WELL	IJ	02/01/2017	ERIW	075-06348	NORTH MINTO J SAND UNIT 1	IJ

General Comment:

P&A Day (2) - High winds, rain and snow have caused delays in P&A process. P&A continues dependant on weather conditions.

Location**Lease Road:**

Type	Access		
comment:	Satisfactory		
Corrective Action:		Date:	

Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	Satisfactory		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Satisfactory	
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Other	# 0		corrective date
Comment:	Remove all equipment upon completion of P&A and begin reclamation process.		
Corrective Action:		Date:	

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 219441 Type: WELL API Number: 075-06348 Status: IJ Insp. Status: IJ**Cement**Cement ContractorContractor Name: Timka ResourcesContractor Phone: 970-667-9861Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging OperationsDepth Plugs(feet range): 4770'Cement Volume (sx): 2

Good Return During Job: _____

Cement Type: _____

Comment:

Set CIBP @ 4770' place (2) sks cement on top of CIBP. Stretched casing to 30", preparing to recover approx. 2200' casing. Weather conditions continue to control scheduling with appropriate safety delays due to wind, rain and snow.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	In Process	Other	In Process			

Comment: Continue BMP's for stormwater erosion management until final reclamation is approved.

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
P&A Day (2)	schureky	04/18/2018