

On April 18, 2018, COGCC Environmental Staff (Alex Fischer) conducted an environmental field inspection of SandRidge Exploration & Production LLC's (SandRidge) Spicer 3-32H Location (Location ID: 324754) API 057-06469. Weather was sunny and temperatures about 25 degrees Fahrenheit.

The following is a summary:

- Oil staining on the ground beneath the catchment containment at the load out area.
- Oil staining on the gravel in secondary containment near Tank # 9007.
- Entrance sign on the ground.

Corrective Actions (CAs):

- **By May 20, 2018**, remediate the oily stains and salty stains beneath catchment containments, valves, fittings, and unions at well head and pump jack.

906.a, Spills/Releases, Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff., Immediately to stop and clean up 24 hours to remove free fluids. 30-days to remove stained soil.

Train and educate staff and contract personnel on house keeping with zero spills within the load out areas, and that staining beneath valves, fittings, unions, etc. may be a result of leaking/loose/weeping valves, fitting, unions, etc. that should immediately be addressed.