

GOLDEN EAGLE MINE E-1A API# 05-071-06411 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 – INSPECTION DATE: APRIL 19, 2018
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 680102745




PHOTO 1: FACING NORTH TOWARD THE GOLDEN EAGLE MINE E-1A PAD RECLAMATION. A DIRT BERM WAS INSTALLED PARALLEL TO THE EXISTING LEASE ROAD TO RE-DIRECT THE RUN ON FROM THE LEASE ROAD UPGRADIENT OF LOCATION AWAY FROM THE RECLAMATION AREA. IT'S POSSIBLE THAT GRAVEL FROM THE ACCESS ROAD MAY HAVE MIGRATED ONTO LOCATION. SOME COMMON MULLEIN ROSETTES WERE FOUND AND REMOVED FROM THE LOCATION. THE EARTH DISTURBANCE WAS HYDRO-SEEDED WITH AN APPROVED COLORADO PARKS AND WILDLIFE (CPW) SEED MIX TO PROMOTE THE ESTABLISHMENT OF VEGETATION.

GOLDEN EAGLE MINE E-1A API# 05-071-06411 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 – INSPECTION DATE: APRIL 19, 2018
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 680102745




PHOTO 2: FACING NORTH TOWARD THE GOLDEN EAGLE MINE E-1A PAD RECLAMATION. RUN OFF FROM THE UPGRADE LEASE ROAD FLOWS TOWARD THE RECLAMATION AREA. THE DIRT BERM RE-DIRECTS RUN OFF.

GOLDEN EAGLE MINE E-1A API# 05-071-06411 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 – INSPECTION DATE: APRIL 19, 2018
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 680102745



PHOTO 3: FACING NORTH, THE ACCESS ROAD TO GOLDEN EAGLE MINE E-1A PAD WAS RECONTOURED TO MATCH THE SURROUNDING TERRAIN. GRADING TECHNIQUES WERE INSTALLED ON THE CONTOUR. THE EARTH DISTURBANCE WAS HYDRO-SEEDED WITH AN APPROVED COLORADO PARKS AND WILDLIFE (CPW) SEED MIX TO PROMOTE THE ESTABLISHMENT OF VEGETATION.

GOLDEN EAGLE MINE E-1A API# 05-071-06411 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 – INSPECTION DATE: APRIL 19, 2018
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 680102745



PHOTO 4: FACING NORTHWEST, THE ACCESS ROAD TO GOLDEN EAGLE MINE E-1A PAD WAS RECONTOURED TO MATCH THE SURROUNDING TERRAIN. GRADING TECHNIQUES WERE INSTALLED ON THE CONTOUR. (4) WATER BARS WERE INSTALLED TO DIVERT WATER OFF THE R.O.W. THE EARTH DISTURBANCE WAS HYDRO-SEEDING WITH AN APPROVED COLORADO PARKS AND WILDLIFE (CPW) SEED MIX TO PROMOTE THE ESTABLISHMENT OF VEGETATION.

GOLDEN EAGLE MINE E-1A API# 05-071-06411 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 – INSPECTION DATE: APRIL 19, 2018
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 680102745



PHOTO 5: FACING SOUTHEAST FROM RAIL LINE, THE ACCESS ROAD TO GOLDEN EAGLE MINE E-1A PAD WAS RECONTOURED TO MATCH THE SURROUNDING TERRAIN. GRADING TECHNIQUES WERE INSTALLED ON THE CONTOUR. (4) WATER BARS WERE INSTALLED TO DIVERT WATER OFF THE R.O.W. THE EARTH DISTURBANCE WAS HYDRO-SEEDING WITH AN APPROVED COLORADO PARKS AND WILDLIFE (CPW) SEED MIX TO PROMOTE THE ESTABLISHMENT OF VEGETATION.