

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401623162

Date Received:

04/27/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 1001 17TH STREET #1000

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Fitzgerald, Edie

719-845-2108

ediefitzgerald@tcenergy.us

Amato, Joseph

719-845-2110

josephamato@tcenergy.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 680102757

Inspection Date: 03/07/2018

FIR Submit Date: 03/20/2018

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 1001 17TH STREET #1000

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 307410

Location Name: GOLDEN EAGLE MINE-633S67W Number: 21SESW County: LAS ANIMAS

Qtrqtr: SESW Sec: 21 Twp: 33S Range: 67W Meridian: 6

Latitude: 37.153979 Longitude: -104.896101

FACILITY - API Number: 05-071-00 Facility ID: 217626

Facility Name: GOLDEN EAGLE MINE Number: NW-3-6-95

Qtrqtr: SESW Sec: 21 Twp: 33S Range: 67W Meridian: 6

Latitude: 37.153979 Longitude: -104.896101

CORRECTIVE ACTIONS:

1 CA# 115049

Corrective Action: Perform Final Reclamation per COGCC 1004 Rules, including but not limited to recontouring, replacement of topsoil, and seeding of site. Install and maintain appropriate BMPs to stabilize location until uniform vegetation establishes across all disturbance areas. All reclamation activities to be complete by May 15, 2018.

Date: 05/15/2018

Response: CA COMPLETED

Date of Completion: 04/26/2018

Recontoured the well pad to match the surrounding terrain. Replaced the top soil during reclamation activities. Grading techniques were installed on the contour to promote ground infiltration and to prepare the soil for

Operator seeding. A dirt berm was used as perimeter sediment control. All disturbed soils were stablized by hydro seeding  
Comment: with an approved Hill Ranch seed mix.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: The corrective actions have been addressed regarding COGCC FIR Doc # 680102757

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: \_\_\_\_\_

Title: Sr. Environmental Tech.

Date: 4/27/2018 1:02:50 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401623177	Well pad reclamation photos
-----------	-----------------------------

Total Attach: 1 Files