

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#		corrective date
Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Ancillary equipment	# 1		
Comment: Electrical box			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	100 BBLS	STEEL AST		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 210091 Type: WELL API Number: 043-40028 Status: PR Insp. Status: PR

Producing Well

Comment: [PR - 317b \(Protected Waters\)](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
317b - High side of Arkansas River. Well is 400 ft South of river and 25 ft in elevation up from river.	duranj	05/08/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687901915	Lease sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4456793
687901916	Well pad	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4456794
687901917	Electrical box	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4456795