

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401635741

Date Received:

05/10/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 1001 17TH STREET #1000

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Fitzgerald, Edie

719-845-2108

ediefitzgerald@tcenergy.us

Amato, Joe

719-845-2110

josephamato@tcenergy.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 680102754

Inspection Date: 03/07/2018

FIR Submit Date: 03/20/2018

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 1001 17TH STREET #1000

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 307409

Location Name: GOLDEN EAGLE MINE-633S67W Number: 21NWSE County: LAS ANIMAS

Qtrqtr: NWSE Sec: 21 Twp: 33S Range: 67W Meridian: 6

Latitude: 37.154448 Longitude: -104.891449

FACILITY - API Number: 05-071-00 Facility ID: 217625

Facility Name: GOLDEN EAGLE MINE Number: 3N-2-95

Qtrqtr: NWSE Sec: 21 Twp: 33S Range: 67W Meridian: 6

Latitude: 37.154448 Longitude: -104.891449

CORRECTIVE ACTIONS:

1 CA# 115034

Corrective Action: Perform Final Reclamation per COGCC 1004 Rules including re-contouring, seeding of site and reclamation of access road. Install appropriate BMPs to stabilize location until vegetation establishes. All Reclamation Activities to be complete by May 15, 2018.

Date: 05/15/2018

Response: CA COMPLETED

Date of Completion: 05/09/2018

Operator Comment: Reclamation of the well pad and access road are complete. The top soil was utilized during reclamation activities. Grading techniques were installed on the contour. All disturbed soils were stabilized by hydro seeding with an approved Hill Ranch seed mix. The silt fence, stakes, location sign and top soil sign were removed from location.

The erosion issues were all corrected during the reclamation. (3) water bars were installed on the access road and (1) on the well pad. See attached photo log for details.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: Sr. Environmental Tech.

Date: 5/10/2018 9:32:28 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

401635778	Reclamation photos
-----------	--------------------

Total Attach: 1 Files