

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401617844
Date Received:
04/24/2018

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Lindsey Rider	970-285-2711	lrider@caerusoilandgas.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680102614
Inspection Date: 01/19/2018 FIR Submit Date: 01/25/2018 FIR Status: _____

Inspected Operator Information:

Company Name: ENCANA OIL & GAS (USA) INC Company Number: 100185
Address: 370 17TH ST STE 1700
City: DENVER State: CO Zip: 80202-5632

LOCATION - Location ID: 323947

Location Name: COUEY-67S92W Number: 5NWSE County: GARFIELD
Qtrqr: NWSE Sec: 5 Twp: 7S Range: 92W Meridian: 6
Latitude: 39.473811 Longitude: -107.688260

FACILITY - API Number: 05-045-00 Facility ID: 211329

Facility Name: COUEY Number: 5-10
Qtrqr: NWSE Sec: 5 Twp: 7S Range: 92W Meridian: 6
Latitude: 39.473811 Longitude: -107.688260

CORRECTIVE ACTIONS:

1 ☒ CA# 114196

Corrective Action: CA#1) Comply with the Reclamation rules to remove, all, Abandoned gathering line risers, and flowline risers (Regardless of Ownership) within three months of plugging the associated Well. Reclaim any areas disturbed by removal activities. CA Date is left at CA Date from Previous Insp of 6/30/17.

CA#2) Reinstall failed Reclamation, enable site to drain, remove Debris. Install BMPs to stabilize site while Vegetation establishes. Reclamation Activities to commence no later than 6/1/16.

Date: 06/01/2016

Response: CA COMPLETED

Date of Completion: 04/24/2018

Operator Comment: CA#1: The riser on the pipeline right of way belongs to Summit Midstream. The riser exists within their permitted pipeline right of way and is associated with their active pipeline. The riser is not associated with the Couey 5-10 well pad. Please contact Summit Midstream for further details regarding their riser and associated pipeline.

CA#2: The landowner still wishes to keep the property as it currently exists and the revised (Caerus) Landowner Variance Request was re-submitted 4/24/2018 Doc#401617714.

COGCC Decision: Approved pending re-inspection

COGCC Representative: CA Inspection has been sent to Summit Midstream. Variance request has been resubmitted though it was returned to Draft for clarification 5/10/18. This Doc should have been submitted as Factual Review Request.

OPERATOR COMMENT AND SUBMITTAL

Comment: Attention: Lou Colby

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lindsey Rider

Signed: _____

Title: EHS Lead

Date: 4/24/2018 9:31:10 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401617844	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files