

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401621604  
Date Received:  
04/27/2018

FIR RESOLUTION FORM

CA Summary:  
2 of 3 CAs from the FIR responded to on this Form  
2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10447  
Name of Operator: URSA OPERATING COMPANY LLC  
Address: 792 BUCKHORN DR  
City: RIFLE State: CO Zip: 81650  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
<u>Knudson, Dwayne</u>	<u>970-456-3335</u>	<u>dknudson@ursaresources.com</u>
<u>Leonard, Mike</u>		<u>mike.leonard@state.co.us</u>
<u>Fischer, Alex</u>		<u>alex.fischer@state.co.us</u>
.		<u>dnr_COGCCEngineering@state.co.us</u>
<u>Deranleau, Greg</u>		<u>greg.deranleau@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 689300908  
Inspection Date: 04/17/2018 FIR Submit Date: 04/17/2018 FIR Status:

Inspected Operator Information:

Company Name: URSA OPERATING COMPANY LLC Company Number: 10447  
Address: 1600 BROADWAY ST STE 2600  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335538

Location Name: VALLEY FARMS Number: F PAD County: GARFIELD  
Qtrqr: NWS Sec: 14 Twp: 6S Range: 92W Meridian: 6  
W  
Latitude: 39.525698 Longitude: -107.642649

FACILITY - API Number: 05-045-00 Facility ID: 291066

Facility Name: VALLEY FARMS Number: F3  
Qtrqr: NWS Sec: 14 Twp: 6S Range: 92W Meridian: 6  
W  
Latitude: 39.525698 Longitude: -107.642649

CORRECTIVE ACTIONS:

1  CA# 115913

Corrective Action:

Date: 04/20/2018

Properly treat or dispose of oily waste in accordance with Rule 907.e.. Contact area COGCC EPS  
E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 907. Contact COGCC EPS staff.  
48-hrs To perform cleanup. 5 days to contact Area EPS

Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Response: CA COMPLETED

Date of Completion: 04/19/2018

Operator Comment: Drip pans cleaned out along with stains. Leaking tank valve fixed. See photo. Remaining stained gravel inside containment is scheduled to be cleaned May 7-9th.

COGCC Decision: Approved

COGCC Representative:

2  CA# 115914

Corrective Action: Notified Ursa.

Date:

Response: CA COMPLETED

Date of Completion: 04/17/2018

Operator Comment: No actual action, should have been a comment, not a Corrective Action.

COGCC Decision: Approved

COGCC Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Please send to Darin Holtz. The stained soil outside containment has been cleaned up along with the drip pan inside containment and gravel immediately beneath. Carlos Lujan has inspected the location. An action plan was submitted to clean the remaining gravel for this location on May 7th - May 9th.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Dwayne Knudson

Signed:

Title: Environmental Manager

Date: 4/27/2018 11:05:43 AM

#### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401621604	FIR RESOLUTION SUBMITTED
401622913	Stains outside containment removed
401622915	Drip pan cleaned up along with stain under.

Total Attach: 3 Files