

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401663637

Date Received:

06/05/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10679

Name of Operator: LOGOS OPERATING LLC

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87415

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Fischer, Alex</u>		<u>alex.fischer@state.co.us</u>
<u>Rowley, Darren</u>	<u>505-947-4974</u>	<u>drowley@logosresourcesllc.com</u>
<u>Sessions, Tamara</u>	<u>505-324-4145</u>	<u>tsessions@logosresourcesllc.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 688800087

Inspection Date: 04/27/2018

FIR Submit Date: 05/02/2018

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: LOGOS OPERATING LLC

Company Number: 10679

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87415

LOCATION - Location ID: 333122

Location Name: NORTHWEST CEDAR HILL Number: 23NWNW County: LA PLATA  
32-10-N32N10W

Qtrqtr: NWN Sec: 23 Twp: 32N Range: 10W Meridian: N  
W

Latitude: 37.007660 Longitude: -107.907750

FACILITY - API Number: 05-067-00 Facility ID: 213776

Facility Name: NORTHWEST CEDAR HILL Number: 12-23  
32-10

Qtrqtr: NWN Sec: 23 Twp: 32N Range: 10W Meridian: N  
W

Latitude: 37.007660 Longitude: -107.907750

CORRECTIVE ACTIIONS:

1 CA# 116187

Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.1.

Date: 06/01/2018

Response: CA COMPLETED

Date of Completion: 05/25/2018

Operator Comment: We installed a 6' tank inside the fiberglass tank. The fiberglass tank is now acting as secondary containment.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**2** CA# 116188

Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.1.

Date: 06/01/2018

Response: CA COMPLETED

Date of Completion: 05/25/2018

Operator Comment: We installed a 6' tank inside the fiberglass tank. The fiberglass tank is now acting as secondary containment.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

OPERATOR COMMENT AND SUBMITTAL

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Larissa Farrell

Signed: \_\_\_\_\_

Title: Regulatory Technician

Date: 6/5/2018 2:35:18 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

401663643	Photo
401663646	Photo

Total Attach: 2 Files