

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/30/2018

Submitted Date:

05/30/2018

Document Number:

688400187**FIELD INSPECTION FORM**
 Loc ID 319094 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
,		COGCCInspections@extracti onog.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453223	WELL	DG	02/05/2018		123-45983	Coyote Trails 34S-20-12N	WO

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	OTHER		
Comment:	Fracking Operation		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Approx 32' sound walls on South and southwest end of location		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 453223 Type: WELL API Number: 123-45983 Status: DG Insp. Status: WO

Complaint

Comment:

Field Inspector Assigned: Jason E. Gomez

Complaint Received:

Date: 5-30-2018

Complaint Contacted:

Date: 5-30-2018 Time 1440 Hrs

Location #: 319094

Inspection Document #: 688400187

Nature of complaint: Noise

Field Inspector Actions:

On 5-30-2018, I was contacted by COGCC staff in reference to some complaints received by the COGCC in reference to noise, the complaint stated the noise was coming from the Erie area originating from the Extraction, Coyote location.

On 5-30-2018, I attempted to contact the complaints in reference to the noise she was experiencing which she perceived as coming from the Coyote fracking location. I performed a complete site inspection of the Coyote location. I reviewed location records, which did not show any abnormal fracking conditions at the time of the complaints. I reviewed third party sound records at the times of the complaint and at no time did the drilling operation exceed COGCC rules according to the sound study information reviewed. I attached the third party sound results to inspection document.

No violation of COGCC rules were observed at the time of the inspection of the frack operation nor in the surrounding neighborhood.

All information reviewed and site inspection information were submitted to the complaint specialist for further review.

Corrective Action:

Date:

Well StimulationStimulation Company: LibertyStimulation Type: HYDRAULIC FRAC

Other: _____

Observation:

Maximum Casing Recorded: _____ PSI

Tubing: _____

Surface: _____

Intermediate: _____

Production: _____

Instantaneous Shut-In Pressure (ISIP) _____

Bradenhead Psi: _____

Frac Flow Back: Fluid: _____ Gas: _____

Comment: _____

Corrective Action: _____

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688400188	Thir Party sound results	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4488419

