

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401646669

Date Received:

05/21/2018

## FIR RESOLUTION FORM

### CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name

Phone

Email

Shorty, Priscilla

pshorty@hilcorp.com

Ray, Mandy

(505) 599-4083

mray@hilcorp.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 680602616

Inspection Date: 04/12/2018

FIR Submit Date: 04/27/2018

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

### LOCATION - Location ID: 333776

Location Name: ARGENTA 34-10-M34N10W Number: 34NENE County: LA PLATA

Qtrqtr: NENE Sec: 34 Twp: 34N Range: 10W Meridian: M

Latitude: 37.152110 Longitude: -107.915440

### FACILITY - API Number: 05-067- -00 Facility ID: 261507

Facility Name: ARGENTA 34-10 Number: 34-3

Qtrqtr: NENE Sec: 34 Twp: 34N Range: 10W Meridian: M

Latitude: 37.152110 Longitude: -107.915440

### CORRECTIVE ACTIONS:

1 ☒ CA# 116112

Corrective Action: Remove waste and debris.

Date: 05/31/2018

Response: CA COMPLETED

Date of Completion: 05/15/2018

Operator Comment: Waste and debris removed. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2 ☒ CA# 116113

Corrective Action: Mark or remove rig anchors.

Date: 05/31/2018

Response: CA COMPLETED

Date of Completion: 05/15/2018

Operator  
Comment: Rig anchors marked. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

3 ☒ CA# 116114

Corrective Action: Stormwater controls need to be installed to stabilize erosion in the northeastern project area and along the access road.

Date: 05/31/2018

Response: CA COMPLETED

Date of Completion: 05/15/2018

Operator  
Comment: Stormwater controls have been installed to stabilize erosion. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed:

Title: Operations Reg Technician

Date: 5/21/2018 5:59:53 AM

#### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401646669	FIR RESOLUTION SUBMITTED
401646670	ARGENTA 34-10 34-3 CORRECTIVE PHOTOS

Total Attach: 2 Files