

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/06/2018

Submitted Date:

06/13/2018

Document Number:

679100195

FIELD INSPECTION FORM

Loc ID 325849 Inspector Name: KUBECZKO, DAVE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

Findings:

- 1 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Dave Kubeczko		dave.kubeczko@state.co.us	
Naomi Azulai	970-232-1439	naomi.azulai@bp.com	
BP Inspections, All		SanJuanCOGCC@bp.com	

General Comment:

BP AMERICA PRODUCTION COMPANY # 10000
BP Inspections, All SanJuanCOGCC@bp.com
Naomi Azulai 970-232-1439 naomi.azulai@bp.com
Date of Inspection: 06-06-18
Type of Inspection: Form 2A, Fed / Fed, Containment, Stormwater
Location Name: Fischer-Mark Federal B 1 Pad; Fischer-Mark Federal B 1 well
Location ID #: 325849
Location: La Plata County; SESE, Sec 4, T34N, R6W
Form 2A# 401239603
API #: 05-067-07073
Conducted onsite to inspect new construction stormwater BMPs for well pad (perimeter berm, diversion trenches, straw wattles, and other spill stormwater control equipment) and access road (borrow ditch for sediment control), which are in-place and these stormwater controls indicate no offsite migration of fluids or sediment; operator will be abandoning recently drilled and completed well, and will be drilling one additional well sometime in early 2019; site should be inspected once the new well is drilled, completed, flowline tested, and on production.