

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/19/2018

Submitted Date:

06/29/2018

Document Number:

690300287**FIELD INSPECTION FORM**

Loc ID 322388 Inspector Name: Spencer, Stan On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	
Byers, Jim	970 -876 -9056	jbyers@blm.gov	NRS
Arauzo, Steven		steven.arauza@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

General Comment:

Pre-closure Pit #112128 inspection. Three small pits on on location. Pits include: 1) ~500 gallon , open-top, poly tank in 15'x15'x3' excavation with mesh net south of wellhead. 2) 15'x15'x3' netted eathern pit at separator. Dry but staining observed beneath discharge pipe. 3) 15'x15'x3' netted earthen pit north of separator, also dry with stains at discharge pipe.

Close pit in compliance with COGCC rules. Perform closure in accodance with approved F-27 including representative soil samples confirming Table 910-1 compliance. Notify COGCC a minimum of 72 hrs prior to any excavation activity. All reclamtion must be performed in compliance with COGCC 1000 rules plus BLM requirements for federal surface lands.

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690300288	045-06153 isnp photos 6-19-18	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4510199