

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401699527
Date Received:
07/11/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

| Contact Name | Phone | Email |
|-------------------------|---------------------|---------------------------------|
| <u>Beebe, Sabre</u> | <u>970-779-9398</u> | <u>Sabre.Beebe@bpx.com</u> |
| <u>Leonard, Mike</u> | | <u>mike.leonard@state.co.us</u> |
| <u>Inspections, All</u> | | <u>SanJuanCOGCC@bp.com</u> |

COGCC INSPECTION SUMMARY:

FIR Document Number: 685304999
Inspection Date: 06/28/2018 FIR Submit Date: 07/03/2018 FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 320869

Location Name: MARQUEZ GAS UNIT- Number: 7SWNE County: ARCHULETA
N32N5W
Qtrqtr: SWNE Sec: 7 Twp: 32N Range: 5W Meridian: N
Latitude: 37.035886 Longitude: -107.429784

FACILITY - API Number: 05-007- -00 Facility ID: 205285

Facility Name: MARQUEZ A Number: 1
Qtrqtr: SWNE Sec: 7 Twp: 32N Range: 5W Meridian: N
Latitude: 37.035886 Longitude: -107.429784

CORRECTIVE ACTIONS:

1 CA# 117166

Corrective Action: Install sign to comply with Rule 210.b. Date: 09/02/2018

Response: CA COMPLETED Date of Completion: 07/10/2018

Operator Comment: New sign installed and old sign removed from location and disposed of properly. see attached photos

COGCC Decision: _____

COGCC
Representative: _____

2 CA# 117167

Corrective Action: Clean up and remediate to comply with Rule 907.a.

Date: 07/10/2018

Response: CA COMPLETED

Date of Completion: 07/10/2018

Operator
Comment: Impacted soils have been manually cleaned up and removed from location. These soils will be remediated by depositing in the soil box at the Durango Operations Office and remediated in bulk at IEI in Farmington New Mexico. See attached photos of work completion. An exhaust box has been installed to prevent future staining and exhaust hose has been check for any needed repairs.

COGCC Decision: _____

COGCC
Representative: _____

3 CA# 117168

Corrective Action: Install sign to comply with Rule 210.b.

Date: 08/03/2018

Response: CA COMPLETED

Date of Completion: 07/10/2018

Operator
Comment: New sign has been installed and old sign removed from location

COGCC Decision: _____

COGCC
Representative: _____

4 CA# 117169

Corrective Action: Remove debris to comply with Rule 1003.a.

Date: 10/02/2018

Response: CA COMPLETED

Date of Completion: 07/10/2018

Operator
Comment: Vehicle frame turned into trailer with fencing debris and barb wire debris on S edge of location (abandoned/dumped). This debris belonged to the surface owner. After obtaining owner authorization this has been removed from location and disposed of.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed see attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Compliance Specialist

Date: 7/11/2018 11:10:44 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|------------------------|
| 401699548 | Work completion photos |

Total Attach: 1 Files