

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401700651

Date Received:  
07/12/2018

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Beebe, Sabre</u>	<u>970-779-9398</u>	<u>Sabre.Beebe@bp.com</u>
<u>Inspections, All</u>		<u>SanJuanCOGCC@bp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 685304790  
Inspection Date: 05/24/2018 FIR Submit Date: 05/30/2018 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 312123

Location Name: CLOVIS GAS UNIT A-N33N9W Number: 6SWSE County: LA PLATA  
Qtrqtr: SWSE Sec: 6 Twp: 33N Range: 9W Meridian: N  
Latitude: 37.126838 Longitude: -107.864305

FACILITY - API Number: 05-067-00 Facility ID: 215302

Facility Name: CLOVIS A Number: 1  
Qtrqtr: SWSE Sec: 6 Twp: 33N Range: 9W Meridian: N  
Latitude: 37.126838 Longitude: -107.864305

CORRECTIVE ACTIIONS:

**1** CA# 116599

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Date: 06/30/2018  
Remove free fluids and contact COGCC EPS staff per Rule 906.b.

Response: CA COMPLETED Date of Completion: 06/28/2018

Release was contained and repairs made to equipment by operations upon arrival on location after call from COGCC inspector. Clean up of all impacted soils on location addressed by manual removal and disposal at the

Operator Comment: Durango Office into the soil box where soils will be remediated in bulk in Farmington NM at IEI. See attached photos

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

2 CA# 116600

Corrective Action: Install or repair required BMPs to comply with Rule 1002.f.

Date: 06/30/2018

Response: CA COMPLETED

Date of Completion: 06/28/2018

Operator Comment: Rock rundowns installed to slow down flow and catch sediment and prevent additional cutting. See attached photos.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions addressed see attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: \_\_\_\_\_

Title: Compliance Specialist

Date: 7/12/2018 9:17:23 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401700665	Work completion photos
-----------	------------------------

Total Attach: 1 Files