

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/23/2018

Submitted Date:

08/23/2018

Document Number:

689401561

FIELD INSPECTION FORM

Loc ID 321991 Inspector Name: CONKLIN, CURTIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10515
Name of Operator: GUNNISON ENERGY LLC
Address: 1801 BROADWAY #1200
City: DENVER State: CO Zip: 80202

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
McWilliams, Dan	(970) 986-2927	dan.mcwilliams@oxbow.com	
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	Petroleum Engineer
Donahue, Jessica		jessicadonahue@summiteng.net	
Engineering		dnr_cogccengineering@state.co.us	All Engineering

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208775	WELL	SI	08/21/1981	GW	029-06047	LEON LAKE UNIT 2	TA

General Comment:

This is a routine field inspection, any corrective actions not addressed from previous inspections are still applicable.

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:	Posted Emergency Contact Number 1-970-874-7697		
Corrective Action:			Date:

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

	Type WELLHEAD		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 208775 Type: WELL API Number: 029-06047 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: No production equipment on location. No production on file. MIT on 7/22/15. A well may be temporarily abandoned after passing a successful mechanical integrity test per Rule 326 upon approval of the Director, for a period not to exceed six months. If an operator requests temporary abandonment status in excess of six months the operator shall state the reason for requesting such extension and state plans for future operation. A Sundry Notice, Form 4, or other form approved by the Director, shall be submitted annually stating the method the well is closed to the atmosphere and plans for future operation.

Corrective Action: **Contact COGCC Engineering Group** Date: 09/03/2018

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Stormwater erosion appears to be controlled on the location at this time.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689401568	Leon Lake Unit 2 Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4560735