

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401624728
Date Received:
08/16/2018

FIR RESOLUTION FORM

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Susana Lara-Mesa	303-825-4822	slaramesa@kpk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 690100459
Inspection Date: 04/17/2018 FIR Submit Date: 04/23/2018 FIR Status: _____

Inspected Operator Information:

Company Name: K P KAUFFMAN COMPANY INC Company Number: 46290
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 318749

Location Name: UPRR 43 PAN AM I-61N68W Number: 13NWSW County: WELD
Qtrqr: NWS Sec: 13 Twp: 1N Range: 68W Meridian: 6
Latitude: 40.049643 Longitude: -104.959640

FACILITY - API Number: 05-123-00 Facility ID: 242099

Facility Name: UPRR 43 PAN AM I Number: 30
Qtrqr: NWS Sec: 13 Twp: 1N Range: 68W Meridian: 6
Latitude: 40.049643 Longitude: -104.959640

CORRECTIVE ACTIONS:

1 ☒ CA# 116013

Corrective Action: Comply with COGCC Rule 603.f; Remove trash from well pad. Date: 05/23/2018

Response: CA COMPLETED Date of Completion: 05/23/2018

Operator Comment: Trash, unused concrete debris and electrical conduits were removed. Please see attached pictures.

COGCC Decision: Approved

COGCC
Representative:

2 ☒ CA# 116014

Corrective Action: Repair equipment/ flowline riser (valve); Clean up stained soils in the area of release.

Date: 05/23/2018

Response: CA COMPLETED

Date of Completion: 05/23/2018

Operator
Comment: Stained soil has been removed, leaking bullplug has been repaired. Please see attached picture.

COGCC Decision: Approved

COGCC
Representative:

3 ☒ CA# 116015

Corrective Action: Remove unused equipment per 603.f

Date: 05/23/2018

Response: CA COMPLETED

Date of Completion: 05/23/2018

Operator
Comment: Unused steel pipe barrier on the southwest corner of the well pad was removed. Please see attached picture.

COGCC Decision: Approved

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Susana Lara-Mesa

Signed:

Title: VP of Engineering

Date: 8/16/2018 2:51:38 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
401624728	FIR RESOLUTION SUBMITTED
401624739	Removed stained soil PIC1
401736220	Removed trash and pipe barrier PIC2

Total Attach: 3 Files