

FRAM OPERATING LLC – 10310

API # 05-077-08932 Mansur 33-1

API # 05-077-09470 Mansur 33-1-L

API # 05-077-09471 Mansur 33-1-N

API # 05-077-09473 Mansur 33-1-G

API # 05-077-09475 Mansur 33-1-K

Inspection Date : 8/29/2018



API # 05-077-09471 Mansur 33-1-N



API # 05-077-09470 Mansur 33-1-L

FRAM OPERATING LLC – 10310

API # 05-077-08932 Mansur 33-1

API # 05-077-09470 Mansur 33-1-L

API # 05-077-09471 Mansur 33-1-N

API # 05-077-09473 Mansur 33-1-G

API # 05-077-09475 Mansur 33-1-K

Inspection Date : 8/29/2018



API # 05-077-09473 Mansur 33-1-G



API # 05-077-09475 Mansur 33-1-K

FRAM OPERATING LLC – 10310
API # 05-077-08932 Mansur 33-1
API # 05-077-09470 Mansur 33-1-L
API # 05-077-09471 Mansur 33-1-N
API # 05-077-09473 Mansur 33-1-G
API # 05-077-09475 Mansur 33-1-K
Inspection Date : 8/29/2018



API # 05-077-08932 Mansur 33-1



Tank battery, meter, combustor

FRAM OPERATING LLC – 10310

API # 05-077-08932 Mansur 33-1

API # 05-077-09470 Mansur 33-1-L

API # 05-077-09471 Mansur 33-1-N

API # 05-077-09473 Mansur 33-1-G

API # 05-077-09475 Mansur 33-1-K

Inspection Date : 8/29/2018



Separator