

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401756733  
Date Received:  
09/07/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 6 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10447  
Name of Operator: URSA OPERATING COMPANY LLC  
Address: 792 BUCKHORN DR  
City: RIFLE State: CO Zip: 81650  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Holtz, Darin</u>		<u>darin.holtz@state.co.us</u>
<u>Pesicka, Conor</u>		<u>conor.pesicka@state.co.us</u>
<u>Knudson, Dwayne</u>	<u>(970) 456-3335</u>	<u>dknudson@ursaresources.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 680200172  
Inspection Date: 08/30/2018 FIR Submit Date: 08/30/2018 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: URSA OPERATING COMPANY LLC Company Number: 10447  
Address: 1600 BROADWAY ST STE 2600  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 419380

Location Name: Diemoz Number: A Pad County: GARFIELD  
Qtrqr: NWS Sec: 36 Twp: 5S Range: 92W Meridian: 6  
W  
Latitude: 39.569539 Longitude: -107.672092

FACILITY - API Number: 05-045- -00 Facility ID: 419377

Facility Name: Diemoz Number: A3  
Qtrqr: NWS Sec: 36 Twp: 5S Range: 92W Meridian: 6  
W  
Latitude: 39.569539 Longitude: -107.672092

CORRECTIVE ACTIONS:

1 CA# 118317

Corrective Action: Install sign to comply with Rule 210.b.

Date: 10/01/2018

Response: CA COMPLETED

Date of Completion: 08/31/2018

Sign updated on well head to include phone number.

Operator  
Comment:

COGCC Decision:

COGCC  
Representative:

4 CA# 118320

Corrective Action: Install sign to comply with Rule 210.b.

Date: 10/01/2018

Response: CA COMPLETED

Date of Completion: 08/31/2018

Operator  
Comment:

Completed - see photo

COGCC Decision:

COGCC  
Representative:

5 CA# 118321

Corrective Action: Close or cover all bore holes.

Date: 09/28/2018

Response: CA COMPLETED

Date of Completion: 08/31/2018

Operator  
Comment:

Borehole filled with gravel. See photo

COGCC Decision:

COGCC  
Representative:

6 CA# 118322

Corrective Action: Repair leak within 24 hours.

Date: 08/25/2018

Response: CA COMPLETED

Date of Completion: 08/24/2018

Operator  
Comment:

Bradenhead valve was open per approved Form 4 doc #401420483. Valve was shut 8/24/18 as per emergency phone call (closed within 15 minutes of phone call). Craig Burger requested that Ursa open the bradenhead valve back up on 8/30/18.

COGCC Decision:

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Please send to Shaun Kellerby

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Dwayne Knudson

Signed:

Title: Environmental Manager

Date: 9/7/2018 11:00:29 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
401756745	Wellhead
401756748	Borehole Closed

Total Attach: 2 Files