

STATE OF
COLORADO

DOC# 2302927

Santovena - DNR, Crystal <crystal.santovena@state.co.us>

Fwd: Bondad 33-9#18

1 message

Roy - DNR, Catherine <catherine.roy@state.co.us>

Tue, Sep 11, 2018 at 1:32 PM

To: Crystal Santovena - DNR <crystal.santovena@state.co.us>

Hi Crystal,

Can you please upload the following email correspondence to the well file for the 325175 location? Can we title it Operator/Surface Owner Correspondence? Here is the info from the card:

Here is the information from the card:

Name and Date: Catherine Roy/September 11, 2018

Projects: **325175**

Facilities: Well Locations

Other:

Enter in Database? Yes

Needs Scanning? No

Index Doc? I'm not sure

Return to Office: No

File in Public Room? No

Thank you very much!

----- Forwarded message -----

From: **Rowley, Darren** <Darren.Rowley@wpxenergy.com>

Date: Tue, Jul 14, 2015 at 2:03 PM

Subject: Bondad 33-9#18

To: "Roy - DNR, Catherine" <catherine.roy@state.co.us>

Cc: "Granillo, Lacey" <Lacey.Granillo@wpxenergy.com>, "Knight, Russell" <Donald.Knight@wpxenergy.com>

Ms. Roy,

July 14, 2015

This letter is in response to Document #667100623 dated 6/8/2015 in reference to the Bondad 33-9#18.

This well was drilled in April 1956.

Darren Rowley Production Supervisor with WPX Energy has been in contact with the land owner Jeff Paxton about the debris in question. Mr. Paxton stated that they have been storing their stuff there for 50 years and would like it left alone. This debris is outside of the anchor pattern for the well. With the age of this well the interim reclamation area is not clearly defined. I have included an e-mail from Mr. Paxton stating that this is his material and would like it left alone.

Thank you,

Darren Rowley

Production Supervisor

Colorado/ Cox Canyon/ Middle Mesa Team

Cell#(505)947-4974

Office#(505)333-1835



From: Jeff Paxton [paxton.jeff@gmail.com]
Sent: Tuesday, July 14, 2015 7:32 AM
To: Rowley, Darren
Subject: Fwd: Delivery Status Notification (Failure)

----- Forwarded message -----

From: Mail Delivery Subsystem <mailer-daemon@googlemail.com>
Date: Mon, Jul 13, 2015 at 8:52 PM
Subject: Delivery Status Notification (Failure)
To: paxton.jeff@gmail.com

Delivery to the following recipient failed permanently:

darren.rowley@wpxenerg.com

Technical details of permanent failure:

DNS Error: Address resolution of wpxenerg.com. failed: Domain name not found

----- Original message -----

DKIM-Signature: v=1; a=rsa-sha256; c=relaxed/relaxed;
d=gmail.com; s=20120113;
h=mime-version:date:message-id:subject:from:to:content-type;
bh=NKSRzG0lpmVnfnO+c22Z8DxjrM3j6zw4WZLFkP3ytw=;
b=buqV74lConimpueKvBCutuky6R63TleqVJ9Me1KGx0Cqd9WKyMQWJ3bRchhH/ejs+C
lklyEVvOqr4bwHSSXzVUaaQnxisCGzOen1hrr99STXA1WRbsPR/SzGoD8aN8jVkrRt2jb
mBmHtEmaoSX5Bp5TrHxOc8/CU0pbMoZ4kqZINVScRxVHrSwg/c9mAr1itJAPvMdNO16A
TYx1rEBDogKXZNjAYSHBXdEJDUE7KI5BZCfkCtyFBwqSqNxrYxJuzfPVq4/jjc1Nb2eq
WzknGHOHkYY56GKlmeWvBdHmS2yCrAF+DER6RF428AVD5lum/8b3vRmcJIGVKJaojjeP
8HIA==

MIME-Version: 1.0

X-Received: by 10.50.62.20 with SMTP id u20mr421350igr.54.1436842357263; Mon,
13 Jul 2015 19:52:37 -0700 (PDT)

Received: by 10.107.53.83 with HTTP; Mon, 13 Jul 2015 19:52:37 -0700 (PDT)

Date: Mon, 13 Jul 2015 20:52:37 -0600

Message-ID: <CACfQpy9KsM+sQzSBDB3JvZQL-6=30EbTkvZzvCvcjkscDmUQYw@mail.gmail.com>
Subject: Location 33-9 #18 located on the Paxton ranch
From: Jeff Paxton <paxton.jeff@gmail.com>
To: darren.rowley@wpxenerg.com
Content-Type: multipart/alternative; boundary=047d7bdca6064dc19c051acce35

To whom it may concern the material on the edge of the location is mine and would like it left there. If there is a problem I and WPX will work it out . I don't kneed the state to interfere on my property I own and pay taxes on. Any questions please call Jeff Paxton @[970-749-3414](tel:970-749-3414)

--

Catherine Roy
Southwest Reclamation Specialist



C 970.946.9107

1120 Lincoln Street, Suite 801, Denver, CO 80203 catherine.roy@state.co.us | www.colorado.gov/cogcc