

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401643340  
Date Received:  
05/17/2018

## FIR RESOLUTION FORM

### CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

### Additional Operator Contact:

Contact Name	Phone	Email
Beebe, Sabre		SanJuanCOGCC@bp.com Sabre.Beebe@bp.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 680602572  
Inspection Date: 03/21/2018 FIR Submit Date: 04/03/2018 FIR Status:

### Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303

### LOCATION - Location ID: 306852

Location Name: WEBB-REEDER GAS UNIT B- N34N9W Number: 11SENW County: LA PLATA  
Qtrqr: SENW Sec: 11 Twp: 34N Range: 9W Meridian: N  
Latitude: 37.223723 Longitude: -107.824988

### FACILITY - API Number: 05-067- -00 Facility ID: 269737

Facility Name: WEBB-REEDER B Number: 2  
Qtrqr: SENW Sec: 11 Twp: 34N Range: 9W Meridian: N  
Latitude: 37.223723 Longitude: -107.824988

### CORRECTIVE ACTIONS:

1 ☒ CA# 115520

Corrective Action: Stormwater controls are needed to stabilize stormwater erosion causing tunnelling and channeling within the project area. Date: 05/04/2018

Response: CA COMPLETED Date of Completion: 05/01/2018

Operator Comment: Rock run downs have been installed to address the storm water CA on this location please see attached photos.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: The corrective action for erosions issues has been addressed with the installation of rock rundowns. Previously installed BMP's have been cleaned out and contaminated soils not noted in inspection, but identified during work planning have been excavated from location and disposed of in the soil box at the Durango Operation Center soil box for batch remediation at the IEI facility in NM. Please see attached document.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: \_\_\_\_\_

Title: Compliance Specialist

Date: 5/17/2018 8:19:50 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
401643340	FIR RESOLUTION SUBMITTED
401643347	Work completion photos

Total Attach: 2 Files