

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/13/2018

Submitted Date:

09/13/2018

Document Number:

689701794**FIELD INSPECTION FORM**Loc ID 334912 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256254	WELL	PR	10/13/1999	GW	045-07437	PA 41-6	PR
270605	WELL	PR	02/12/2005	OW	045-09564	PA 341-6	PR
270606	WELL	PR	12/01/2004	OW	045-09565	PA 441-6	PR
270607	WELL	PR	02/14/2005	GW	045-09566	PA 344-31	PR
270627	WELL	PR	02/10/2005	OW	045-09576	PA 541-6	PR

General Comment:

Routine General Field Inspection

Location

Lease Road:			
Type	Main		
comment:	Washing on main road to frontage road.		
Corrective Action	Repair and maintain lease road to comply with rule 204.	Date:	10/15/2018

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-285-9377

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Dead weed debris on well site, access road and tank battery.		
Corrective Action:	Comply with Rule 603.f .	Date:	09/25/2018

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:				corrective date	
Type: Horizontal Heated Separator	# 5				
Comment:					
Corrective Action:				Date:	
Type: Bird Protectors	# 3				
Comment:					
Corrective Action:				Date:	
Type: Plunger Lift	# 5				
Comment:					
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 256254 Type: WELL API Number: 045-07437 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Facility ID: 270605 Type: WELL API Number: 045-09564 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Facility ID: 270606 Type: WELL API Number: 045-09565 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Facility ID: 270607 Type: WELL API Number: 045-09566 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Facility ID: 270627 Type: WELL API Number: 045-09576 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Road ditches are washing and building up with sediment. Sediment blockage forcing flow on to road and into fields. Washing of main road to frontage road.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 10/15/2018

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689701795	Inspection 689701794 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4579119