



RECEIVED
BUREAU OF LAND MGMT.
GRAND JCT. CO

2018 SEP 10 PM 2:11

864 20 Road, Unit A
Fruita, Colorado 81521
(970) 858-8550
FAX (970) 858-8155

P.O. Box 338
Ignacio, Colorado 81137
(970) 563-4000
FAX (970) 563-4116

August 23, 2018

United States Department of the Interior
Bureau of Land Management
Grand Junction Field Office
2815 H Road
Grand Junction, CO 81506

Re: 2800 (COS09000)
COC61214

Dear Ms. Stevens,

In response to your letter regarding the Roan Creek ROW, Maralex submits this plan to be competed in order to bring the evaporation pond into compliance.

1. Remove the damaged liner.
2. Remove and dispose of any contaminated soil within the boundaries of the evaporation pond.
3. Install a new liner that meets all Federal and State regulations.
4. Install a properly functioning leak detection system that includes a function test feature.
5. Reclaim the eroded areas, bring berm into compliance, and recontour and reseed the affected areas with pre-approved seed mixtures.
6. Reclaim the bioremediation site by removal of stock piles of soil, soil preparation for seeding, and reseeding with pre-approved seed mixture.
7. Keep the evaporation pond and ROW in compliance with state, county, and local requirements.

A schedule of the work will be submitted via the appropriate forms for each regulatory organization.

Please let me know of any questions.

Thanks,

Jordan Reid
Maralex Resources, Inc
(970)563-4000
maralextechjr@gmail.com